



Service Request Details

Claim

S3M04NC5

Reference

CC4/HSB23006483/Apa3

Loss Date

13 June 2023

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

15 Jun 2023 8:23:39 AM

Request Date

27 June 2023

Due Date

27 June 2024

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work



Menu

Vehicle Information

Incident Vehicle Registration #

GBD8631G

Make

TPVD Toyota

Model

Hiace

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TEO Kitty

kitty.teo@axa.com.sg

Additional Instructions

WS : MG Solution

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes



Document SubType

Driver's License / IDP

▼

+ Upload Documents

Already Attached

NAME	OID - STATUS OF VOCATIONAL LICENCE- VALID.pdf.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Driver's License / IDP
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	27 June 2023
NAME	OID- Status of Driving Licence - VALID.pdf.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Driver's License / IDP
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	27 June 2023
NAME	REPLY FORM WS.msg.msg
TYPE	Letters and Correspondence
SUBTYPE	Others
AUTHOR	NIKAM Santosh Pandurang
DATE UPLOADED	27 June 2023
NAME	TP VIDEO.mp4
TYPE	Evidence
SUBTYPE	Videos
AUTHOR	TEO Kitty
DATE UPLOADED	27 June 2023
NAME	EMAIL FORM WS FOR TP REG.msg.msg



AUTHOR	NIKAM Santosh Pandurang
DATE UPLOADED	27 June 2023

NAME	GBD8631G TP GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	KUMAR Shailendra
DATE UPLOADED	26 June 2023

NAME	SHC8633K INSD GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	STACEY Ng Pei Sze 2
DATE UPLOADED	15 June 2023
