

# CO-FORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHC8790P

DATE 24.06.2023

MAKE REG.31.08.2021

MODEL : IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR MOULDING RH			cut \$110.10
1	FRONT DOOR HANDLE RH			Rp \$234.80
1	FRONT DOOR HANDLE COVER RH			Rp \$45.00
1	REAR ROCKER PANEL RH			dis \$290.00
1	REAR DOOR MOULDING OUTER RH			cut \$125.30
1	REAR DOOR RH			bt \$1,768.90
	<b>SUB TOTAL</b>			<b>\$2,574.10</b>
	<b>LESS 20%</b>			<b>\$514.82</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$2,059.28</b>
1	FRONT DOOR COMFORT LOGO STICKER			cut \$75.00
1	REAR DOOR COMFORT APP ZIG STICKER			cut \$80.00
				<b>\$155.00</b>
	<b>Labour Charge</b>			
	Panel Beating			525 \$800.00
	Spray Painting Charge			750 \$800.00
	Tuff coat			30 \$90.00
	Remove/refix rear door part			60 \$90.00
	<b>TOTAL LABOUR</b>			<b>\$1,780.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$3,994.28</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfah 07495749  
 up 26/6/23 @ 11am  
 2-3 days  
 p/p missing before paint  
 tanfah C11kank.com

Date/Time: 26.06.2023 08:53

Page : 1

JOB CARD Sales Order: 5901585

JC NO 305558680

Team: ARC Repair TP(CLSO)1

CUSTOMER

R/MS COMFORT TRANSPORTATION PTE LTD  
CUSTOMER NO. 7010045  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
TEL (R) 65508755 (O)  
(P)

REGN NO.: SHC8790P	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ (G3)	DATE/TIME IN 24.06.2023 09:10
YR OF MANU. 31.08.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU194832	COMPLETION DATE/TIME:

DISCOUNT CARD NO.


JOB DESCRIPTION

Accident Date: 24.06.2023  
NATURE: 3P 24.06.2023

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Name:

C No.:

Vehicle No.:

SHC8790P

CHIANG

Exit Pass

Vehicle No.:

SHC8790P

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard