



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23006537/Uny3e2 Date: 07/07/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLR 4093T	Veh. Inspected	SKT 9483U
Policy No.	P10596749R01	Coverage (\$)	0.00
Claim No.	C10023088 /CH	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	28/06/2023
2. Vehicle Particulars & Condition			
Make & Model	NISSAN SYLPHY (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNTBBAB17Z0023706	Colour	WHITE
Odometer	197388 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	8 mm
L/H Front Tyre	205/55 R16	PIRELLI	8 mm
R/H Rear Tyre	205/55 R16	PIRELLI	8 mm
L/H Rear Tyre	205/55 R16	PIRELLI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/06/2023	Inspection Date	03/07/2023
Survey held at	TLM AUTOMOBILE PTE LTD 1 DEFU LANE 6, DEFU INDUSTRIAL PARK A, SINGAPORE 539365		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	