Not Notherital
Resurry B4-paint

AAD2306-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330 CO./ GST Reg. No. 201019626G

SHC5442P

Vehicle No.:

Chassis No.:

Co UEN .:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registriation:

2 7 JUN 2023

SHC5442P

JTDKB3FU203092189

200303878K

TOYOTA

PRIUS GEN 4

25/6/2023

SFH73B/TOKIO

15/4/2021

PART

LIST

	ALL A PERCENT AND LEADING TO SERVICE AND A S		
1	COVER, REAR BUMPER	\$	R 612.68 L
1	COVER, REAR BUMPER, LOWER	\$	M. 27.93 —
1	GUARD, REAR BUMPER, CENTER	\$	Ry 472.19 -
1	SEAL, REAR BUMPER SIDE, LH	\$	Pm 149.21
1	SEAL, REAR BUMPER SIDE, RH	\$	₩ 149.21 X
1	RETAINER, REAR BUMPER SIDE, LH	\$	Dri 167.48
1	REAR BUMPER SIDE RETAINER RH	\$	€ 167.48 X
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	B 419.90
1	REFLECTOR ASSY, REFLEX, LH	\$	kg 49.25
1	REFLECTOR ASSY, REFLEX, RH	\$	€ 49.25 X
1	COVER, REAR COMBINATION LAMP, RH	\$	In 88.41 ⊀
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	1 428.19 Å
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	1 329.49 X
1	COVER, REAR COMBINATION LAMP, LH	\$	1- 88.41 X
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	14 428.19 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	1- 329.49 Å
1	COVER, FLOOR UNDER, RH	\$	220.50
1	COVER, FLOOR UNDER, LH	\$	304.92 7
1	COVER, REAR FLOOR	\$	Mi 290.43
1	COVER, DECK TRIM, REAR	\$	1 159.39 ∧
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	R 824.46
1	PANEL SUB-ASSY, BACK DOOR	\$	R 1,443.86
1	BOARD, BACK DOOR TRIM	•	€ 284.55 X
1	PANEL ASSY, BACK DOOR TRIM, UPPER	•	€ 65.73 X
1	STAY ASSY, BACK DOOR, LH	Č	5 305.66 x
1	STAY ASSY, BACK DOOR, RH	4	4 305.66 ₹
1	HINGE ASSY, BACK DOOR, LH	4	№ 77.18 🗶
1	HINGE ASSY, BACK DOOR, RH	· ·	77.18 X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	SM	3cm 1,156.89
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	•	M 68.88
		4	- W 00.00 -

AAD2306-

5 Rosen 170.00 X

Trans-cab Auto Services Pte Ltd No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel Nc Fax No.: 62571330 CO./ GST Reg. No. 201019626G SHC5442P Ac 68.88 . PLATE, BACK DOOR NAME, NO.1 1 90.30 ORNAMENT SUB-ASSY, BACK DOOR 9,701.23 TOTAL \$ 2,425.31 25% \$ 7,275.92 \$ SPECIAL NETT NU 700.00 22012 \$ **1SET PARKING AID** Me 65.00 6012 \$ **REAR BUMPER CLIP** 1 ~~ 65.00 √ \$ **REAR RH BUMPER RETAINER CLIP** 1 ~~ 65.00 x \$ **REAR LH BUMPER RETAINER CLIP** 1 12 60.00 X \$ **END PANEL INNER TRIM CLIP** Ma 180.00 30/w 1 **REAR BUMPER PROTECTOR** Mr 150.00 80/2 **2 WINDSCREEN SEALANT** Ma 200.00 . WINDSCREEN MOULDING 130.00 3014 WINDSCREEN INNER SPONGE SEAL 1,615.00 TOTAL \$ 8,890.92 **TOTAL PARTS \$ LABOUR** 600.00 301 \$ To rust-proofing of the affected areas. 1,200.00 Sfee Putty and spray painting of the affected portion. \$ Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the 2,000.00 6001 \$ same To transfer of tailgate fittings and conduct water seepage \$ 170.00 601 test. To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair. 170.00 \$

To transfer of tailgate fittings and conduct water seepage

test.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5442P

To transfer of bootlid fittings, attachments and perform

water seepage test.

~~ 170.00 X

AAD2306-

To reinstall rear bumper parking sensor.

170.00 501

To check steering geometry and computer wheel alignment \$_\\$ TOTAL \$

NA 220.00

5,250.00

OVERALL TOTAL \$ 14,140.92

3day,

SA1D236P0001-01 / Ajax Mars Pte Ltd ENTRY DATE & TIME: 25/06/2023 19:08 (SGT) SUBMITTED BY: Sabitra VERSION: 2 (26/06/2023 09:46 (SGT))

© SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

25/06/2023 19:08 (SGT)

Actual Driver

25/06/2023 00:02 (SGT)

Singapore

KALLANG ROAD

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHC5442P

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address Mobile Phone No

Alternative Phone No

TRANS-CAB SERVICES PTE LTD

2XXXXX878K

Claims@transcab.com.sg

(Phone) +65-62876666

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Toyota

Prius

5DR HATCHBACK (AUTO)

Private hire

No - Claiming third party

Taxi

Auto

1798

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

HSBC Life (Singapore) Pte. Ltd VFX/P2413997

DRIVER

Name of Driver

NRIC No Date Of Birth

Occupation

TONG SHIANG BOON SXXXX503B

10/09/1971 Outdoor

Accident report SA1D236P0001

Page 1 of 29

Gender Name

Date Of Driving Pass 06/02/1995 Driving experience 28 YEARS AND 4 MONTHS Male Mobile Number (Phone) +65-97533373 Alt. Phone Number **Email Address** Claims@transcab.com.sg Address Blk 2 Address complement #06-75 Postcode 200002 No Is the driver the policyholder? Hirer If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Collision - Head to Rear Type of Accident **Weather Conditions** Dry Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 No Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Yes Was any other vehicle or property damaged? 2 Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Passenger 1

IRD. SIN MING ROAD, SINGAPUME DIS

Male Gender

DETAILS OF POLICE ACTION

No Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

MY VEHICLE WAS ALREADY STOPPED, STATIONARY TO DROP OFF MY PASSENGER. WHILE COLLECTING THE FARE FROM MY PASSENGER. SUDDENLY I FELT AN IMPACT FROM BEHIND. SAW A VEHICLE HAS ALREADY HIT DIRECTLY INTO MY VEHICLE REAR PORTION. I TOLD MY PASSENGER IF HE FELT UNCOMFORTABLE, HE MAY SEEK FOR MEDICAL ATTENTION. I MIGHT SEEK FOR MEDICAL ATTENTION AS WELL.

ATTACHMENT(S)

Yes Are accident photos available for attachment? Yes Was there any video captured by Car Camera?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFH73B

ACCIDENT DIAGRAM

Policyholder's Signature Date & Time: bliver's Signature

(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Reporting Centre Personnel's Signature Name: NRIC/FIN No.: