

Mei Kwan (LKKAuto)

From: Susan Low <liusbro@ymail.com>
Sent: Friday, 30 June 2023 3:27 PM
To: Admin A; assignments
Subject: Our Ref: GBE7456Y230623 Your Ref: GBE419B
Attachments: GBE7456Y 23062023.mp4; GBE7456Y230623.pdf; GBE7456Y Search.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Categories: HMK

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Vehicle to be surveyed:	GBE7456Y
3rd Party Insured Vehicle:	GBE419B
Date of Accident:	23/06/2023
Location of Accident:	Towards SenKee Logistics
Name of Workshop:	Liu's Brother Auto Engineering Workshop
Address of Survey Location:	No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop as soon as possible.

Kindly arrange

Thank.

Best Regards,

M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730

Date of Survey:	
Name of Authorise Surveyor:	

Susan Low

