

(08/11/13) wef

ASS. REC. BY: *Person*

REF:


CS/SMR 23006586/Rapp3

9559

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SBV 64764*
 at Workshop m/s *VOLKSWAGEN*
 of *ALSTON RD*
 Insured: *SMR*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition) *lan*
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: *61k*
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: *3* days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: *SBV64764* Yr Regn: *2023/P6B*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *SKODA OCTAVIA STYLE 1.0TS ic.c 999*
 Colour: *WHITE* A/C: Insured / Std / NI / NA
 Sp. Reading: *4595* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *TMBBP8NXOPYU42141*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: *225/45R18*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. *6* mm Rear R/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *23/06/23* D.O.I. *04/07/23*
 Survey held at *VOLKSWAGEN*
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
4/2 REAR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>REPAIR LIMIT - 70k</i>
	<i>Repair finalised final fig \$2144.40, 3 days chkd @ 4186.81, 667.2</i>

Date/Time, File Pass to? : Prell. Report
 1) *26/7 2023* : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format : *TP*
 Lump Sum / I.B.I.: (\$) *2144.40*)
 Days Of Repair: *3*
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$)) _____ \$ + RS ___ \$
 : Interview (\$)) Photos
 : Tech. Invs (\$)) Others
 : Weekend (\$)) _____
 TOTAL _____

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
ONG
CHWEE KOK
26 LUXUS HILLVIEW
SINGAPORE 804502

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

28-06-2023
5211041856
195000106C
30001
2023017120/ 1
26-06-2023
Dass Anthonidas
Christopher

License plate SBV6476G	Model code NX34LDS0	First registration 23-02-2023	VIN TMBBP8NX0PY042141	Model OCTAVIA M-HEVSTY TS81/1.0 A7F	Mileage 20
---------------------------	------------------------	----------------------------------	--------------------------	--	---------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5E7807393	Unbekannt	1	pcs.	48.60	#6	48.60	52.49
5E7807394	LHR BUMPER BRACKET (SIDE)	1	pcs.	48.60	#6	48.60	52.49
5E7807394	Guide Profile RHS	1	pcs.	48.60	#6	48.60	52.49
3Q0919133 9B9	Seal Ring Satin Black	4	pcs.	6.10	#6	24.40	26.35
5WA919275B GRU	Sensor Primed	1	pcs.	194.63	#6	194.63	210.20
5E7945105	Unbekannt	1	pcs.	61.29	#6	61.29	66.19
5E6807521 9B9	LHR REFLECTOR	1	pcs.	273.69	#6	273.69	295.59
	Unbekannt	1	pcs.	273.69	#6	273.69	295.59
	REAR LOWER SPOILER	1	pcs.	273.69	#6	273.69	295.59
	LABOUR	1	pcs.	840.00	#6	840.00	900.00
	Spray Painting	1	pcs.	800.00	#6	800.00	860.00
	MS FIRST CARPITAL DIRECT				#6	2,520.00	2,721.60
	DOA:25/06/2023				#6	2,406.00	2,592.00
	TP VEH NO:SHF30L						
	SURVEY BY:						

Quotation valid till 03-07-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	5,571.21	8%	506.50	6,331.21	6,837.71
Total	760.00	5,571.21		506.50	6,331.21	6,837.71

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
ONG
CHWEE KOK
26 LUXUS HILLVIEW
SINGAPORE 804502

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
28-06-2023
5211041856
195000106C
30001
2023017120/ 1
26-06-2023
Dass Anthonidas
Christopher

License plate SBV6476G	Model code NX34LDS0	First registration 23-02-2023	VIN TMBBP8NX0PY042141	Model OCTAVIA M-HEVSTY TS81/1.0 A7F	Mileage 20
---------------------------	------------------------	----------------------------------	--------------------------	--	---------------

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Handwritten notes:
From
Hp 90010068
3 days
04/07/23
Resy after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/06/2023 18:58 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	25/06/2023 06:59 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONGSIDE 23 LEXUS HILL VIEW AND 25 LEXUS HILL VIEW
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBV6476G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ONG CHWEE KOK
NRIC No	SXXXX955G
Email Address	ockpat@gmail.com
Mobile Phone No	(Phone) +65-98564211
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Skoda
Model	Octavia
Variant	OCTAVIA M-HEVSTY TS81/1.0 A7F
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1000

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2004739265-01

DRIVER

Name of Driver	ONG CHWEE KOK
NRIC No	SXXXX955G
Date Of Birth	25/05/1960
Occupation	Indoor

Date Of Driving Pass	01/12/1979
Driving experience	43 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98564211
Alt. Phone Number	-
Email Address	ockpat@gmail.com
Address	26 LUXUS HILLVIEW
Address complement	-
Postcode	804502
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHF30L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	LOH NGIAN KWONG
NRIC No	SXXXX933B

Contact Number (Phone) +65-96466557
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature] 26/6/2023 12:20 PM


[Signature]

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



vJun2022

A - SBV64766

B - SHF30L

Describe Circumstance of the Accident

I am the owner of SKODA OCTAVIA SBV64T6G. On 25 June 2023 my vehicle (SBV64T6G) was parked outside 25 Luxus Hill - alongside 23 Luxus Hill View and 25 Luxus Hill View and it my vehicle was stationary. At 6:59am 25 June 2023, my neighbour called to inform me that my vehicle was hit by a "STRIDES" Taxi vehicle No. SIF30L. This has happened while the taxi-driver was making a 3-point turn. At that time of happening, the road ^{condition} was dry and traffic was clear. Damage was found and seen on the left side of the bumper. Details of the taxi-driver was provided per below:

Taxi-Driver Name : LEE NGIAN KWONG
 NRIC NO : S2004933B
 Mobile No : 96466557

Declaration

I/We declare the foregoing particulars are true in every respect.

 26/6/2023 1220pm

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

vJun2022