



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23006599/Kqp3m4	
			Date: 11/07/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKV 8856Z	Veh. Inspected	SJL 8655B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2302580/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	30/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053ZEE106126484	Colour	METALLIC LIGHT GREEN
	Odometer	574734 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	FRONWAY	8 mm
	L/H Front Tyre	205/55 R16	FRONWAY	8 mm
	R/H Rear Tyre	205/55 R16	FRONWAY	7 mm
	L/H Rear Tyre	205/55 R16	FRONWAY	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/06/2023	Inspection Date	30/06/2023
	Survey held at	AUTHORIZE WORKSHOP PTE LTD 160 SIN MING DRIVE #03-19, SIN MING AUTOCITY, SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	