

✓

Kenneth

1

AUTHORIZE WORKSHOP PTE LTD

160, Sin Ming Drive, #03-19, Sin Ming Autocity, Singapore 575722

Tel: 64560226 Fax: 64584500

Registration No: 201603203R

Not Authorized

1/1 Surp & 4000 Max

Painting After Paint

ESTIMATE

Mr **Low Fang Hao**

Blk 491E Tampines St 45, #07-208
Singapore 524491

Date : 30th June 2023

Veh No : **SJL 8655B**

Make/Model : **Toyota Altis**

Chassis No : **MR053ZEE106126484**

Date of Acc : **27.06.23**

TP Veh No : **SKV 8856Z**

S/No	Qty	Description	Unit Price	Amount
------	-----	-------------	------------	--------

Materials

1	1 pc	Bonnet		\$ 883.20 X
2	2 pcs	Bonnet Hinge L/R	\$ 61.80	\$ 123.60 X
3	1 pc	Frt Bumper		\$ 584.00 ✓
4	1 pc	Frt Bumper Logo		\$ 35.80 ✓
5	2 pcs	Frt Bumper Retainer L/R	\$ 55.25	\$ 110.50 ✓
6	2 pcs	Frt Bumper Bracket L/R	\$ 32.55	\$ 65.10 X
7	1 pc	Frt Bumper Reinforcement		\$ 396.50 X
8	1 pc	Frt Bumper Inner Sponge		\$ 111.50 X
9	2 pcs	Frt Bumper Fog Lamp Garnish L/R	\$ 84.60	\$ 169.20 X
10	1 pc	Frt Grille		\$ 353.70 ✓
11	1 pc	Frt Bumper Lower Grille		\$ 107.80 ✓
12	1 pc	Frt Engine Undershield		\$ 146.50 ✓
13	2 pcs	Headlamp L/R	\$ 568.70	\$ 1,137.40 ✓
14	1 pc	Bonnet Lock		\$ 94.70 ✓
15	1 pc	Radiator Support Panel		\$ 2,136.30 X
16	1 pc	Centre Brace Panel		\$ 132.70 ✓
17	1 pc	Radiator 1450		\$ 1,920.80 X
18	1 pc	Radiator Spare Tank		\$ 175.60 X
19	1 pc	Air Con Condensor		\$ 1,559.60 X
20	1 pc	Auxillary Fan Assy 1211-50		\$ 657.30 X
				\$ 10,901.80
Less 25%				\$ 2,725.45
Parts Total				\$ 8,176.35

Special Nett

1	1 set	Frt Bumper Clips		\$ 45.00 ✓
2	1 set	Undershield Clips		\$ 40.00 ✓
3	1 set	Frt License Plate		\$ 40.00 ✓
Special Nett				\$ 125.00

Labour

1	To remove & rearrange electrical wirings, check lightings	\$ 80.00 201
2	To remove, replace air con parts, recharge aircon gas.	\$ 120.00 1001
3	To remove, replace radiator, top up coolant.	\$ 100.00 501
4	To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$ 1,000.00 5001
5	Putty and respray painting on affected portions.	\$ 800.00 6001
6	Rust proofing on affected portions.	\$ 100.00 X
Labour		\$ 2,200.00

Labour : \$ 2,200.00

Total Parts & Labour : \$ 10,501.35

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for Authorize Workshop Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	281B
Vehicle Details	
Vehicle No.:	SJL8655B
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4821078
Chassis No.:	MR053ZEE106126484
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	15 Dec 2008
First Registration Date:	15 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,786.00
COE Rebate Amount:	\$1,252.00
Total Rebate Amount:	\$1,252.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Jun 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/06/2023 13:30 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	27/06/2023 17:23 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	WOODLANDS AVE 3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL8655B
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LOW FANG HAO
NRIC No	S8726281B
Email Address	PATRICKLOWFH@GMAIL.COM
Mobile Phone No	(Phone) +65-96412935
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5119838359-02

DRIVER

Name of Driver	LOW FANG HAO
NRIC No	S8726281B
Date Of Birth	28/08/1987
Occupation	Outdoor

Date Of Driving Pass	20/07/2007
Driving experience	15 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96412935
Alt. Phone Number	-
Email Address	PATRICKLOWFH@GMAIL.COM
Address	BLK 491E TAMPINES STREET 45 #07-208
Address complement	-
Postcode	524491
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Woodlands East Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18007679999
Police Station Address	3 Woodlands Drive 63 Singapore 737890
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ATTACHED POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH OWNER

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV8856Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TAI CHIA FU
NRIC No	S8680268F
Contact Number	(Phone) +65-86959567
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Report No: T/20230627/2095

* Driver with 30 days Medical leaves *

Remark: - 3rd party election at: -

160 Sin Ming Drive
#03-18/19 Sin Ming Autocity
Singapore 575722
Tel: 6456 0226 Fax: 6458 4500
Email: emautosolution@singnet.com.sg

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Bik 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)




**SINGAPORE
POLICE FORCE**


T/20230627/2095

1 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20230627/2095

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/06/2023 19:27		Vide Report No.:		Station Diary No.: 101	
Informant's Particulars					
Name of Informant: LOW FANG HAO		Address: APT BLK 491E TAMPINES STREET 45 #07-208 SINGAPORE 524491			
ID Type / ID No.: NRIC NO / S8726281B		Contact No.: Home/Office:		Mobile: 96412935	
Nationality: SINGAPORE CITIZEN		Email: patricklowfh@gmail.com			
Sex: Male	Age: 35	Date of Birth: 28/08/1987	Type of Informant: Driver		
Race: Chinese			Language:		
Occupation: PRIVATE HIRE DRIVER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 27/06/2023 17:20	Type of Location: T-Junction
Location: WOODLANDS AVENUE 3				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJL8655B	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Slightly Damaged	0
SKV8856Z	Car	MERCEDES BENZ	E 250 SEDAN (R17)	Red	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20230627/2095

2 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20230627/2095

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJL8655B	NTUC Income Insurance Co-Operative Limited	5119838359-02	15/12/2022	14/12/2023

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LOW FANG HAO		ID No.	S8726281B
Related Vehicle	SJL8655B (Car)		Contact No.	96412935
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	TAI CHIA FU		ID No.	S8680268F
Related Vehicle	SKV8856Z (Car)		Contact No.	86959567
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 27/06/2023 at about 1720hrs, I was driving my car SJL8655B along Woodlands Avenue 3 turning right towards Woodlands Street 13 on first lane. I stopped at the T-junction as the traffic light was red at that point of time. When the traffic light turned green, I started to move off and was looking towards the right side. Out of a sudden, I noticed that there was an on-coming car SKV8856Z from the opposite side of the road going straight towards me. I tried to brake however the front right side of the car collided with the front of my car. I went out of my car to make a check. I manage exchange particulars and take photos of the accident. Both parties agreed to go to the police station to lodge a police report.

No traffic police or ambulance attended to the accident. Due to the accident, the front of my car is dented and scratched, and front plate number is also dented. The front right side of the car is scratched and slightly dented, the right headlight cracked.

I wish to state that both parties were not injured. I have an in-car camera in my car, and it recorded the accident.

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20230627/2095

3 of 3

Report No. T/20230627/2095

CONTINUATION OF REPORT

Signature of Officer Recording The Report:

L /
SCSGT(1) MUHAMMAD RAFIQ
ZULHILMI BIN ZULKIFLEE

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
27/06/2023 19:27

Officer In Charge Of Case:
TP / GIA /
SR STAFF SGT LEE GUANG HUI
Contact No.: 65476204

Classification Of Case:

NP168



T/20230628/2022

2 of 3

Report No. T/20230628/2022

Continuation of CSF For NP168

Driver			
Name	Low Fang Hao	ID No.	S8726281B
Related Vehicle	SJL8655B (Car)	Contact No.	96412935
Hospital/Clinic	KINDRED FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/06/2023	Date Discharge	28/06/2023
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Tai Chia Fu	ID No.	S8680268F
Related Vehicle	SKV8856Z (Car)	Contact No.	86959567
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Facts.

CSF amendment report for original report T/20230627/2095.

To add on that the driver of vehicle SKV8856Z had failed to comply with the red traffic light signal and drove forward causing the collision. My vehicle SJL8655B was turning into Woodlands Street 13 as the green arrow traffic light signal was on.

Due to the collision, I sustained neck and back pain and was given 3 days MC from the doctor.

That's all.