

A.S. P.C. BY:

REF:

CC4/III. 23006616/DYA³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 2564 B Yr Regn: March 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 cc 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 692117 T/Radio: Insured / Std / NI / NAEng No: D4FDHU730219C/Nr: KMHLEB4HUM*GU085898Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: 11

BS / DUN / ENJOYA / GY / FS / LZA / MRC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: S mm Rear: S mmR/Bal: S mm L/Bal: S mmL/Bal: S mm D.O.A. 27/06/2023 D.O.I. 30/06/2023Survey held at: CDGE Loyang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>III SHB 3395P</u>
<u>13/07/23</u>	<u>found 2/S 1,150/- with 2 days of rep</u>

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format: _____

I union from 11 P to 12

☐ : Prel. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/06/2023
Vehicle Reg. No.:	SHA2564B	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	24/03/2016
Vehicle Colour:	BLUE	Chassis No:	KMHLB41UMGU085898
Engine No:	D4FDHU730219		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	4,454.60
Miscellaneous Items	11.00
Labour	1,500.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,965.60
+ GST 8.00% (S\$)	477.25
Nett Amount (S\$)	6,442.85

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

28/6 @ 14:00 hrs

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2023) Lim Tien Siong
Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA2564B/28/06/2023 14:00
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH <i>Yes</i>	20.00	0.00	*2,707.70 FL <i>X</i>
2	1		*REAR DOOR RH <i>Yes</i>	20.00	0.00	*2,416.80 FL <i>X</i>
3	1		*FRONT DOOR (COMFORTDELGRO) RH <i>Hic</i>	0.00	0.00	*75.00 F <i>✓</i>
4	1		*REAR DOOR ZIG APPS RH <i>Hic</i>	0.00	0.00	*80.00 F <i>✓</i>
5	1		*FRONT DOOR ADVERTISEMENT STICKER RH <i>Hic</i>	0.00	0.00	*100.00 F <i>✓</i>
6	1		*REAR DOOR ADVERTISEMENT STICKER RH <i>Hic</i>	0.00	0.00	*100.00 F <i>✓</i>

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,479.50
- List Item Discount on L Items (\$\$)	1,024.90
Total Parts (\$\$)	4,454.60

ComfortDelGro Engineering Pte Ltd/SHA2564B/28/06/2023 14:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

SH 355.00

Estimates on Miscellaneous Items

No Qty Particulars

Lim Tien Siong

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer) *HCC*

11.00 ✓

Sub Total (\$)

11.00

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

800.00 *560/-*

2 SPRAY PAINTING

New

600.00 *500/-*

3 TUFF KOTE

New

100.00 *20/-*

1080.00

Gross Labour Cost (\$)

1,500.00

ComfortDelGro Engineering Pte Ltd/SHA2564B/28/06/2023 14:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

30/06/2023 @ 1700hr

H12 John

2pm

2 day.

2
ngn

LKK Auto

8

1446.00

1/s 1,150/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 28.06.2023 13:52 Page : 1

Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 5902064 JC NO305559140

STOMER	REGN NO: SHA2564B	MILEAGE
MS COMFORT TRANSPORTATION PTE LTD STOMER NO. 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	MAKE: HYUNDAI MODEL I-40 YR OF MANU. 24.03.2016 CHASSIS CODE KMHLB41UMGU085898	FUEL E.....1/2.....F DATE/TIME IN 28.06.2023 09:45 TARGET DATE COMPLETION DATE/TIME:
COUNT CARD NO.		

Merimen


JOB DESCRIPTION

LS
India

SNB
3395P

Ident Date: 27.06.2023
RE: 3P 27.06.2023 LKK-
LABOR CODE
PB

DESCRIPTION
PANEL BEATING-SHA2564B-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
Acknowledgement Slip No.: SHA2564B LIMTS	Exit Pass Vehicle No.: SHA2564B
Signature/Date	Date