



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23006637/Kvy3e2 Date: 14/07/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKH 8114E	Veh. Inspected	WC 4994S
Policy No.		Coverage (\$)	0.00
Claim No.	C10023182/SR	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	03/07/2023
2. Vehicle Particulars & Condition			
Make & Model	ISUZU CYH52S (M)	c.c	15681
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JALCYH52SC7000070	Colour	WHITE / BLUE
Odometer	474784 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5 (D)	UNIRUN	2/3 mm
L/H Front Tyre	295/80 R22.5 (D)	UNIRUN	2/3 mm
R/H Rear Tyre	295/80 R22.5 (D/D)	TOP RUNNER	6/6/7/7 mm
L/H Rear Tyre	295/80 R22.5 (D/D)	TOP RUNNER	6/6/7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/06/2023	Inspection Date	04/07/2023
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	