

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/07/2023



User ID : GohKK2

Section A - Accident Details

Registration Number	SMB242D
Case Reference Number	BUS/06/23/5052
Registration Date	27/12/2011
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Azmi Bin Saaid
Type of Accident	Side Swipe
Accident Date and Time	30/6/2023 6:12 AM
Accident Reported Date and Time	30/6/2023 11:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB242D - RIGHT FRONT PORTION PC6907P (TP) - INSURED WITH INCOME
Prepared Date and Time	3/7/2023 10:09 AM
Chassis Number	WMAA22ZZ7C7001253
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$896.33	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,272.33	\$0.00
Lump Sum Total	\$3,250.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	03/07/2023 10:18 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/07/2023

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00						
Total Labour			\$1,590.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00						
Total Spray Painting & Panel Beating			\$786.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW:FRONT,RH,FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	
6010073	Body	F01001-CW262	DOME:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	
6009984	BODY RH	A01001-CW571	PANEL,SIDE:R3,FOR MAN A22 BUS	1.00	\$266.00	100.00	\$0.00	Repair	
Total					\$5,303.10		\$1,120.41		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									