

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23006643/Tny3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557				21-07-2023		
INCOME CENTRESINGAPORE 189557			Code:	INC4		
1.		Policy Portioulors				
1.	. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. PC 6907P Veh. Inspected SMB 242D					
	Policy No.	1 C 09071	Covera		0.00	
	Claim No.	MT/1229871-002	Exces	<u> </u>	0.00	
	Assign From	W171223071-002	Assign	,	03/07/2023	
2.	Assign From	Vahiala Bartir	_		00/01/2020	
Z.	Vehicle Particulars & Condition Make & Model MAN NL320F c.c 10518					
	Engine No.	HIDDEN	C.C	f Dog	2011	
	Chassis No.	WMAA22ZZ7C7001253	Year o		GREEN	
	Odometer	988111	Steerin		IN ORDER	
	Brakes	IN ORDER	Modifi		NIL	
	General	GOOD	WOUTH	Cation	INIL	
3.						
J.	Size Make Balance					
	R/H Front Tyre	275/70 R22.5	FALKE	N	8 mm	
	L/H Front Tyre	275/70 R22.5	FALKE		8 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	FALKE		8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	FALKE		8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
5.	DAMAGES SEE DETAILS. General Information					
J.	Accident Date	30/06/2023	1	tion Date	03/07/2023	
	Survey held at	STRIDES AUTOMOTIVE SERVI		and it butto	00,0172020	
	Jan voy nota at	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.						
ou.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	, ,					
JD.	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					
	ESTIMATED ROTTINAL TENIOD FOR INEL AIR. 2 WORKING Days					