

## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 17/07/2023

User ID : CatherineLee

### Section A - Accident Details

Registration Number	SMB242D
Case Reference Number	BUS/06/23/5052
Registration Date	27/12/2011
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Azmi Bin Saaid
Type of Accident	Side Swipe
Accident Date and Time	30/6/2023 6:12 AM
Accident Reported Date and Time	30/6/2023 11:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118789
Special Instruction to ARC, if any	SMB242D - RIGHT FRONT PORTION PC6907P (TP) - INSURED WITH INCOME
Prepared Date and Time	3/7/2023 10:09 AM
Chassis Number	WMAA22ZZ7C7001253
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$795.00
Total Spray Cost	\$786.00	\$446.00
Total Spare Part Cost	\$896.33	\$896.33
Total Other Cost	\$0.00	(\$248.20)
<b>TOTAL COST</b>	<b>\$3,272.33</b>	<b>\$1,889.13</b>
<b>Lump Sum Total</b>	<b>\$3,250.00</b>	<b>\$1,900.00</b>
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kok Khoon Goh	Taufikh (LKK)
ARC / Surveyor Sign Off Date	03/07/2023 10:18 AM	03/07/2023 5:11 PM
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/07/2023

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	\$795.00
<b>Total Labour</b>	<b>\$1,590.00</b>	<b>\$795.00</b>

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	\$446.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$786.00</b>	<b>\$446.00</b>

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$248.20)
<b>Total Other Costs</b>	<b>\$0.00</b>	<b>(\$248.20)</b>

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW:FRONT,RH,FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace
6010073	Body	F01001-CW262	DOVE:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	Repair
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
6009984	BODY RH	A01001-CW571	PANEL,SIDE:R3,FOR MAN A22 BUS	1.00	\$266.00	100.00	\$0.00	Repair	Repair
<b>Total</b>					<b>\$5,303.10</b>		<b>\$1,120.41</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									