

ASS. REC. BY:

REF:

AIS / 23006648 / K9p3

*C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK 3315Y

Yr Regn:

01.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1597

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

98504

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC5650GT00084

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

215/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

1/7/23

D.O.A.

4/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/7 11/5y @ 4850 Cash 17/11/23 (Red @ 7579.64, 61%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

4850

TOTAL

Authentic

EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emautosolution@singnet.com.sg

Not Authorized
11/10/03 @ 4850h
Resurvey After Paint
7 days

Vehicle number: SLK3315Y

Vehicle Made & Model: HONDA CIVIC

Qty List Items

1	Rear bumper	617.20
2	Rear bumper side retainers - L/R @ 48.50	
1	Rear door - LH	798.90
1	Rear door outer handle	
1	Rear door glass outer moulding	
1	Rear door glass run channel	
1	Rear door glass regulator	341.70
1	Rear door frame chrome moulding	
1	Rear door insulation	
1	Rear door inner lock	
2	Rear door inner trim board	540.20
1	Rear door w/strip	
1	Rear door glass guide	
2	Rear door hinges @ 48.60	
1	Rear door checker	
1	Rear fender - LH	812.30
1	Rear fender glass w/moulding	Prt? 155.90
1	Rear fender inner shield	
1	Rear fender inner panel	
1	Rear fuel lid	
1	Rear sport wheel - LH	
1	Rear shock absorber - LH	
1	Rear top control arm	
1	Rear lower control arm	
1	Rear trailing arm	
1	Rear knuckle arm	
1	Rear wheel hub bearing	314.20
1	Rear windscreen moulding	
1	Rear taillamp - LH	

	Amount \$	
mg/cm	733.70	✓
mls/cm	97.00	✓
R	967.50	✓
Sn	182.20	X
Sn	161.30	X
Sn	189.60	X
Di	612.70	✓
Sn	181.90	X
na	120.30	X
R	288.90	X
mg/cm	761.60	✓
Sn	142.60	X
Sn	89.20	X
R	97.20	X
Sn	48.50	X
R	934.60	✓
na	311.50	✓
cm	126.60	✓
R	581.60	X
Sn	97.90	X
Sn	862.60	X
Sn	286.60	X
Sn	210.50	X
Di	310.60	✓
Sn	531.80	X
R	428.90	✓
na	481.60	✓
na	97.70	✓
Sn	381.60	X

Sub-total 10,318.30

Less 20% 2,063.66

Total List 8,254.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 2

Acknowledged by Repairer

Signature:

Date:

Vehicle number: SLK3315Y

Vehicle Make & Model: HONDA CIVIC

Special Nett Items

1 set Rear bumper clip
1 set Rear door black tape
1 set Rear fender glass sealant
1 set Rear windscreen sealant
1 Rear tyre
1 set Side sill panel garnish clip

Mr	45.00	✓
Mr	120.00	✓
Mr	60.00	30sn
Mr	80.00	40sn
Mr	300.00	70sn 140sn
Mr	80.00	X
Total Special Nett		685.00

Labour charges

To remove, refix rear windscreen / fender glass
To remove, refix rear interior trims to assist repair
To remove, refix rear undercarriage
To reinstall Rear fuel tank to assist repair
To check wheel alignment
To respray undercoating
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

300.00	1201
150.00	1001
300.00	1601
120.00	601
120.00	601
100.00	601
1,200.00	6501
1,200.00	8001
Total Labour	3,490.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12,429.64

R030451
3.7.23 11:54
SLK3315Y
160-0318



SLK3315Y

Honda : Civic FC/FK4-8 Type A
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°43'	-0°43'	-0°48' 0°12'
5°29'	5°29'	4°48' 5°48'
0°05'	0°05'	-0°05' 0°05'
15°19'	15°19'	
14°36'	14°36'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°44'	-0°44'	-0°48' 0°12'
4°24'	4°24'	4°48' 5°48'
-0°06'	-0°06'	-0°05' 0°05'
15°05'	15°05'	
14°21'	14°21'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°00'	0°00'	-0°45' 0°45'
1°05'	1°05'	
0°14'	0°14'	
-0°01'	-0°01'	-0°09' 0°09'

Rear : Left

Actual	Before	Specified Range
-3°04'	-3°04'	-1°57' -0°27'
-0°12'	-0°12'	0°02' 0°09'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°23'	-1°23'	-1°57' -0°27'
0°03'	0°03'	0°02' 0°09'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-1°41'	-1°41'	-0°45' 0°45'
-0°09'	-0°09'	0°05' 0°19'
-0°08'	-0°08'	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	275F
Vehicle Details	
Vehicle No.:	SLK3315Y
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2023
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	R16B21601120
Chassis No.:	MRHFC5650GT000841
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,640.00
Original Registration Date:	12 Jan 2017
First Registration Date:	12 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$20,896.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jan 2027
PARF Rebate Amount:	\$13,582.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$17,928.00
Total Rebate Amount:	\$31,510.00

The information contained herein is correct as at 03 Jul 2023

OK