

Accident
Occupation
Date Of Birth
Name of
NIC No

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO SHA9470S

MAKE : TOYOTA

MODEL : PRIUS

DOA 27.06.123

INS. INCOME

MVA JUMANI

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRT BUMPER	1		\$ <i>for</i> 586.18
FRT BUMPER CLIPS	10		\$ <i>net</i> 22.00
FRT FENDER LH	1		\$ <i>for</i> 1,111.93
FRT FENDER EMBLEM LH	1		\$ <i>net</i> 86.50
FRT BUMPER SIDE BRACKET	1		\$ <i>cur</i> 82.30
FRT SIDE MIRROR ASSY LH	1		\$ <i>X M</i> 1,390.10
FRT SIDE MIRROR COVER LH	1		\$ <i>ant</i> 141.90
SUB TOTAL		2030.81	\$ 3,420.91
LESS 25%			\$ 855.04
DISCOUNTED TOTAL		1523.10	\$ 2,565.15
FRT DOOR COMFORT LOGO			\$ <i>ant</i> 75.00
LESS 10%			7.5
SUB TOTAL		67.50	\$ 67.50
LABOUR CHARGE			
PANEL BEAT			\$ 525 800.00
SPRAYPAINT			\$ 800 1,000.00
CHECK WIRING			\$ <i>44X</i> 50.00
TUFF KOTE			\$ 30 50.00
<i>Tanphim 97495749</i>			1355
<i>WP 28/6/23 0315pm</i>			
<i>c/s Posung after repair</i>			
<i>2 (3) days</i>			
<i>for phic c/ltankur</i>			
TOTAL LABOUR		2945.60	\$ 1,900.00
ESTIMATE TOTAL		115\$1700	\$ 4,471.90
		23 days	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.