

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO SHA9470S

MAKE : TOYOTA

MODEL : PRIUS

DOA 27.06.123

INS. INCOME

MVA JUMANI

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRT BUMPER	1		\$ <i>th</i> 586.18
FRT BUMPER CLIPS	10		\$ <i>net</i> 22.00
FRT FENDER LH	1		\$ <i>bt</i> 1,111.93
FRT FENDER EMBLEM LH	1		\$ <i>net</i> 86.50
FRT BUMPER SIDE BRACKET	1		\$ <i>cur</i> 82.30
FRT SIDE MIRROR ASSY LH	1		\$ <i>X</i> 1,390.10
FRT SIDE MIRROR COVER LH	1		\$ <i>cut</i> 141.90
SUB TOTAL			\$ 3,420.91
LESS 25%			\$ 855.04
DISCOUNTED TOTAL			\$ 2,565.15
 FRT DOOR COMFORT LOGO			\$ <i>cut</i> 75.00
LESS 10%			7.5
SUB TOTAL			\$ 67.50
LABOUR CHARGE			
PANEL BEAT			\$ 525 800.00
SPRAYPAINT			\$ 800 1,000.00
CHECK WIRING			\$ <i>X</i> 50.00
TUFF KOTE			\$ 30 50.00
<i>Tanphin 97495747</i>			
<i>wp 28/6/23 03/5pm</i>			
<i>c/b Bsmg after repair</i>			
<i>2-3 days</i>			
<i>for Mr C Whankun</i>			
TOTAL LABOUR			\$ 1,900.00
ESTIMATE TOTAL			\$ 4,471.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

8/18

Date/Time: 28.06.2023 13:41

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5902061

JC NO305559029

OMER S CITYCAB PTE LTD OMER NO 7010070 ESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (R) (P) (O)	REGN NO: SHA9470S	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4)27.06.2023 21:07	DATE/TIME IN
	YR OF MANU. 13.09.2017	TARGET DATE
	CHASSIS CODE JTDKB3FU303563217	COMPLETION DATE/TIME:


Accident Date: 27.06.2023
Time: 3P.27.06.23

JOB DESCRIPTION

YQ 60561

NO LABOR CODE

DESCRIPTION



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

o.: SHA9470S

JU INCOME

Vehicle No.:

SHA9470S

Service Advisor

Signature/Date

Name of Service Advisor

Date

ed to Service Reception upon collection

To be kept by Security Guard