

REF: CS1/LAW23006668/Dvy3

Special Instruction:

LS : \$3200 / 4 DAYS

ASSIGNMENT (Office)

From (Person): RINA MUNIR of RIAZ LLC Date/Time: 04/05/2023
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: ADVANCED AUTOMOTIVE

Workshop: EQUATOR BROTHERHOOD

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FC 9119X Insured: FBQ 7319Y
at Workshop m/s EQUATOR BROTHERHOOD Tel: _____
of 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800

Policy No: SS/sm/2022000176.Sompo Claim No: WAN.VK.518405.N KCP

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 07/02/2020

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 14/7/23 Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 7 days)

Date/Time: 14/7/23 Submit Final Fig \$980, 3 days (Red \$ 2220 / 69 %; Original 4 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____