

Your Ref: SS/sm/2022000176.Sompo

Date: 27th Jul 2023

Our Ref: CS1/LAW23006668/Dvy3e2

M/s Kelvin Chia Partnership1 Harbourfront Ave
#14-01 Keppel Bay Tower
Singapore 098632

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FC 9119X
INSURED VEHICLE: FBQ 7319Y
ACCIDENT DATE: 07/02/2020**

We thank you for your instruction on 04/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FC 9119X from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Survey report by Priority Services with colour photographs.
- c) Final Repair Bill of FC 9119X from M/s Equator Brotherhood.
- d) Singapore Accident Statement and Police Report of Vehicles FC 9119X.
- e) Colour damaged vehicle photographs of FC 9119X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FC 9119X
Make & Model	: Yamaha GDR155A (AEROX)
Chassis Number	: MH3SG4640JJ044441
Year of Registration	: 2018
Engine Capacity	: 155 cc

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.