



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23006702/Kny3m4 Date: 07/07/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 209L	Veh. Inspected	XE 6803A	
Policy No.	P10193655R04	Coverage (\$)	0.00	
Claim No.	C10023189 /CD	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	03/07/2023	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FV70 (A)	c.c	10677	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	FV70HSA10018	Colour	MULTI COLOUR	
Odometer	127384 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80R22.5	DURATURN	6 mm	
L/H Front Tyre	295/80R22.5	DURATURN	6 mm	
R/H Rear Tyre	275/70R22.5 (D/D)	HILO	5/5/6/6 mm	
L/H Rear Tyre	275/70R22.5 (D/D)	HILO	5/5/6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2023	Inspection Date	04/07/2023	
Survey held at	RS AUTO SERVICES 160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		