

ASS. REC. BY:

REF:

AG2 / 2300.6702/Kny3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

XE 6803A Yr Regn: 10, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda FV70

C.G.

10677

Colour

Multi Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

127389

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FV7015A.10018

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

G/H

R:

295/80R22.5

275/70R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MICTOHTSU / FIRT / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

55

66

mm

L/Bal.

6

mm

L/Bal.

55

66

mm

D.O.A.

30/6/23

D.O.I.

4/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/7 8670.00 Cash (Red, \$1040, 60%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

400H

Vehicle Details

Vehicle No.:

XE6803A

Vehicle to be Exported:

Yes

Intended Deregistration Date:

01 Jul 2023

Vehicle Make:

MITSUBISHI

Vehicle Model:

FUSO FV70HSK2VDEA

Primary Colour:

White

Manufacturing Year:

2021

Engine No.:

470912C0568044

Chassis No.:

FV70HSA10018

Maximum Power Output:

-

Open Market Value:

\$115,866.00

Original Registration Date:

21 Oct 2021

First Registration Date:

21 Oct 2021

Transfer Count:

0

Actual ARF Paid:

\$5,794.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

20 Oct 2031

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$40,010.00

COE Rebate Amount:

\$32,008.00

Total Rebate Amount:

\$32,008.00

The information contained herein is correct as at 01 Jul 2023

OK

RS AUTO SERVICES

160, SIN MING DRIVE . SIN MING AUTOCITY

06-01 SINGAPORE 575722

EMAIL : rsautoservices88@gmail.com / 93825367

Not withain
 1 day
 @ 670/h
 Murray After Rain

Date : 3 Jul 2023

QUOTATION - THIRD PARTY CLAIM

Auto And General Insurance

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 30 Jun 2023

VEH. No : XE 6803 A / MITSUBISHI

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : INCOME INSURANCE

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : SGW 209 L			
1	REAR No.PLATE	\$ <i>nd</i> 60.00	<i>25sn</i>
2	REAR No.PLATE LAMPS	\$ <i>nd</i> 300.00	<i>—</i>
1	60KM/H STICKER	\$ <i>nd</i> 30.00	<i>15sn</i>
1	REAR CARRIAGE END PANEL	REPAIR	
TOTAL S/N :		\$ 390.00	
GRAND TOTAL PARTS :		\$ 390.00	
AMOUNT BRING FORWARD :		\$ 390.00	

LABOUR CHARGES .

Labour charges to do cutting , repair , replace accident affected area

\$ 600.00 *801*

Anti rust

\$ *nn* 120.00 *x*

To do spray painting work

\$ 600.00 *2501*

TOTAL LABOUR :

\$ 1,320.00

GRAND TOTAL PARTS & LABOUR :

\$ 1,710.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: