


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLP 4255D
 at Workshop m/s Boonbu
 of Panason Crescent
 Insured: SMR
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 52K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lim Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP 4255D Yr Regn: 2017 / Jun
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: TOYOTA VIOS 1.5E CUT c.c. 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 401513 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MHF B29F3902011340

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/50R16
 R: 2"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>28/06/23</u>		D.O.I. <u>04/07/23</u>	

Survey held at BoonbuDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 26K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

) \$ + RS \$ SI

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____)



Borneo Motors

ichcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 01/07/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	NSP151R	CEXRKT Q1	05/06/2017	SLP4255D	0	22849	66TP/SLP4255D/300623	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFB29F3902011340		2NRX155836	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SHB5669H ACC DATE: 30/06/23 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:						50 100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST						198.00
3	B	BP-LAB2 R/I INTERIOR TRIMMING TO FAC REPAIR						396.00
4	B	BP-LAB2 TRANSFER BOOTLID MECHANISM						396.00
5	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR						198.00
6	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL						396.00
7	B	BP-RES2 RESRPAY ACC AFF AREA						3280.00
8	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR						198.00
9	1	K52023-0D100 REINFORCEMENT SUB-AS ?			1.00	451.50		451.50
10	2	K52156-0D080 SUPPORT, RR BUMPER S			1.00	31.30		31.30
11	3	K52155-0D090 SUPPORT, RR BUMPER S			1.00	31.30		31.30
12	4	K52576-0D240 RETAINER, RR BUMPER			1.00	162.90		162.90
13	5	K52575-0D240 RETAINER, RR BUMPER			1.00	162.90		162.90
14	6	K52159-0U908 COVER, RR BUMPER, L			1.00	706.90		706.90
15	7	S52161-0K040 PIECE, RR BUMPER			4.00	5.30		21.20
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte. Ltd	
		Document No.	3 Media Close	
		0	#01-03/06	
		Document Date	Singapore 138498	
		01/07/2023	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	05/06/2017	SLP4255D	0	22849	66TP/SLP4255D/300623

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFB29F3902011340	2NRX155836	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	8	K58307-0D250 PANEL SUB-ASSY, BODY	1.00	968.00		968.00
17	9	K58387-0D160 PLATE, RR FLOOR FINI	1.00	309.30		309.30
18	0	K64503-0D040 ARM SUB-ASSY, LUG CO	2.00	77.20		154.40
19	1	K64401-0D160 PANEL SUB-ASSY, LUGG	1.00	1071.10		1071.10
20	2	K64461-0D130 WEATHERSTRIP, LUGGAG	1.00	224.80		224.80
21	3	K64610-0D080 LOCK ASSY, LUGGAGE C	1.00	120.40		120.40
22	4	K75442-0D250 PLATE, LUGGAGE COMPT	1.00	58.50		58.50
23	5	K90975-T2006 EMBLEM, SYMBOL	1.00	68.00		68.00
24	6	K75444-0D460 PLATE, LUGGAGE COMPT	1.00	45.60		45.60
25	7	K81550-0D550 LAMP ASSY, RR COMBIN	1.00	433.40		433.40
26	8	K81560-0D550 LAMP ASSY, RR COMBIN	1.00	433.40		433.40
27	9	K81580-0D190 LAMP ASSY, RR, RH	1.00	256.80		256.80
28	0	K81590-0D150 LAMP ASSY, RR, LH	1.00	256.80		256.80
29	1	SPZ061-0D035 24 BACK SENSOR GREY METALLIC	1.00	149.90		149.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer's Signature

Please acknowledge receipt of vehicle

Charge Summary

Parts	6,118.40
Labour	8,726.00
Sublet	0.00
Lubrication/Fluid	0.00
Others	0.00

Total	14,844.40
GST 8.00%	1,187.55
Less	0.00
Amount Due	16,031.95

Customer Copy

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLP4255D
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2NRX155836
Chassis No.:	MHFB29F3902011340
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,855.00
Original Registration Date:	05 Jun 2017
First Registration Date:	05 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$7,855.00
PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2027
PARF Rebate Amount:	\$5,105.00
Intended COE Rebate Particulars	
COE Expiry Date:	04 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$20,184.00
Total Rebate Amount:	\$25,289.00

The information contained herein is correct as at 06 Jul 2023

OK