

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2304652

INV Date 19/07/2023

Reference CS/EQI23006729/Kqy3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SGP 75S

Insured Veh. GBF 5049Y

Claim No. DM23HO01410/JT

Policy No. DMCPHQ22-003907

Accident Date 28/06/2023

Inspection Date 10/07/2023

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (8%)	12.80
Grand Total	172.80

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Au	itomok	pile
	EQ INSURANCE C	OMPANY LTD	Re	ef:	CS/EQI23006729/Kqy3e2
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		Da	ate:	19/07/2023
			Co	ode:	EQI
1.		Policy Particulars	- THIRD PARTY C	LAIM	
	Insured Veh.	GBF 5049Y	Veh. Inspected		SGP 75S
	Policy No.	DMCPHQ22-003907	Coverage (\$)		0.00
	Claim No.	DM23HO01410/JT	Excess (\$)		0.00
	Assign From	JAIME TAY	Assign Date		04/07/2023
2.		Vehicle Partic	culars & Condition		
	Make & Model	B.M.W. 730I (A)	c.c		1998
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	WBA7E02020G913442	Colour		METALLIC GREY
	Odometer	106031 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make		Balance
	R/H Front Tyre	245/40Z R20	MICHELIN		5 mm
	L/H Front Tyre	245/40Z R20	MICHELIN		5 mm
	R/H Rear Tyre	275/35Z R20	MICHELIN		6 mm
	L/H Rear Tyre	275/35Z R20	MICHELIN		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DI	ETAILS.			
5.		General Information			
	Accident Date	28/06/2023	Inspection Date		10/07/2023
	Survey held at	ALAN'S UNITED AUTO PTE LTD)		
	BLK 7 SIN MING INDUSTRIAL ESTATE				
		#01-76 SINGAPORE 575642			
5a.		Re	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.	D)IN ACCORDANC	·	Days of Repair	INIOE	DINLEMING.
00.	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	•	Vorki	ng Days
					<u> </u>



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 75S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR N/S TAILLAMP (WCP)	CUT	900.00	900.00
1	REAR BUMPER FASCIA (WCP)	CRACKED	1,250.00	1,250.00
1	REAR N/S BUMPER SIDE RETAINER (WCP)	DISTORTED	230.00	230.00
2	REAR N/S BUMPER PARKING SENSOR @\$195.00 (WCP)	SHORTED (1PC ONLY)	390.00	195.00
1	RR N/S BUMPER LOWER SIDE CHROM (WCP)	DENTED	180.00	180.00
1	REAR N/S BUMPER REFLECTOR (WCP)	SERVICEABLE	80.00	-
1	REAR BUMPER LOWER CHROME (WCP)	DENTED	180.00	180.00
1	N/S TAILLAMP CENTRE CHROME MOULDING (WCP) (ADDITIONAL)	CRACKED	140.00	140.00
	COST PLUS 10%		335.00	307.50
			3,685.00	3,382.50
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY REPLACED PARTS.		800.00	300.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.		700.00	250.00
			1,500.00	550.00
	GRAND TOTAL		5,185.00	3,932.50

RECOMMENDED COST OF REPAIRS			3,932.50
-----------------------------	--	--	----------

Report Ref No. CS/EQI23006729/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

Vehicle Insured : GBF5049Y (EQ) Accident Date : 28-06-2023 Date: 11-07-2023

Our Ref: 023141 / CHAN

CHONG KIM WHEY
C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR BMW730LI SGP75S

1 PC N/S TAILLAMP CENTRE CHROME MOULDING

ADD 10% \$140.00 \$154.00

Singapore Dollars One Hundred Fifty Four Only

SV10236U0003 / Vin's Motor Pte Ltd [575722] ENTRY DATE & TIME: 30/06/2023 15:43 (SGT) SUBMITTED BY: YEE SHU Φ YAW VERSION: 1 (30/06/2023 15:43 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/06/2023 15:43 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 28/06/2023 17:19 (SGT) Exact Location of Accident Singapore Additional Location Information SLE TOWARDS BKE BEFORE MANDAI EXIT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGP75S INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner CHONG KIM WHEY NRIC No S7576191J Email Address PEAKTOP75@GMAIL.COM Mobile Phone No (Phone) +65-88338113

VEHICLE PARTICULARS

Manufacturer **BMW** Model 730LI LED NAV HUD SR RCP Variant

Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to

Alternative Phone No

No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 1998

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMPCSNW00086272304

DRIVER

Name of Driver **CHONG WEI SONG** NRIC No T0170357E Date Of Birth 27/06/2001 Occupation Indoor

Date Of Driving Pass 21/12/2020 Driving experience 2 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-88338113 Alt. Phone Number Email Address CHONGWEISONG2001@GMAIL.COM Address BLK 741 WOODLANDS CIRCLE #12-431 Address complement Postcode 730741 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Child Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT SAME AS SKETCH ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Reasons for not uploading a video of the accident SD CARD WITH OWNER **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number **GBF5049Y**

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

GBF5049Y

COMMERCIAL STATES OF THE STATES OF THE

NRIC No	S9721823D
Contact Number	(Phone) +65-88687475
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signatule / Date & Time 30.06.33

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



1

Describe Circumstance of the Accident
At 28 June 2023, around 1719 his. I was driving townia woodland Avenue 2 exit whereby I got reasonated by a Van from the back due to the van being words to stop. I broked in time to stop, but the van beingl failed to do so and swirl left to avoid me but still hit the left rear of my vehicle.
Tropies in time to other hill the wan belong failed to do on any shall be used use
but still hit the left cell of my vanicle.
The repair will be done at ALAN'S UNITED AUTO PTE LTD.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signatural Date & Vine
30.06.23

Driver's Signature (if driver is not the policyholder) / Date & Time

Wings yer

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R


PHOTOGRAPHS FOR VEHICLE NO. SGP 75S


INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGP 75S

RE-INSPECTION











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGP 75S

RE-INSPECTION





