

(08/11/13) wef

ASS. REC. BY: Alan

REF:

CS/EQ123006749/RVY3

2424

**ASSIGNMENT**

From:

Date:

Veh No:

SDQ 3268M

Yr Regn:

2017 / Jun

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SDQ 3268M

Make:

KIA NIRO HYBRID 1.6 GDI DCT 5/R C.C 1580

at Workshop m/s

CYCLE &amp; CARRIAGE

Colour:

GREEN

A/C: Insured / Std / NI / NA

of

205, PANDAN GARDEN

Sp. Reading

94822

T/Radio: Insured / Std / NI / NA

Insured: GBG 5599X

EQ1

Eng/No:

C/No:

KNAC81CVH5079490

Policy No.

Gen. Cond: Good / Fair / Poor / Burnt

Claims No. DM23HO01375/JT

Steering: Inorder / Jammed / Leaked / Burnt or

Sum Insured:

Excess:


Brake: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F:

205/60R16

R:

u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

64K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

24/06/23

D.O.I.

11/07/23

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CYCLE (P4)

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 39K

2/8/23

Final fig \$9507 confirmed by email (Red 9814, 50%)

Date/Time, File Pass to?



: Preli. Report

Days Of Repair: 6

1)



: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2) 3/8/23-typist

Add Fee:



: Site Insp (\$

): S + RS, SI



: Interview (\$

): Photos



: Tech. Invs (\$

): Others



: Weekend (\$

TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$ 9507

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	26/06/2023 14:50 (SGT)
Reported by	Actual Driver
Date of Accident	24/06/2023 10:06 (SGT)
Exact Location of Accident	Near 83 Whampoa Dr, Singapore 320083
Additional Location Information	CTE BEFORE EXIT 7B
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDQ3268M
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN KWAI SIM
NRIC No	S1537242G
Email Address	KENDRICKTAY@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97209008
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Niro
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1580

#### INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2005918614-01

#### DRIVER

Name of Driver	KENDRICK TAY
NRIC No	S9329098D
Date Of Birth	12/08/1993
Occupation	Indoor



Date Of Driving Pass	08/11/2014
Driving experience	8 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97209008
Alt. Phone Number	-
Email Address	KENDRICKTAY@HOTMAIL.COM
Address	103 CORPORATION WALK
Address complement	-
Postcode	618480
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	PAN JINGYI JOHANNA
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SUMMARY AND SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILES ARE TOO LARGE

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG5599X
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Commercial vehicle
Name of Driver .....	-
Contact Number .....	-
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-



**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan

A: SDQ3268M  
B: CBG5599X

CTE BEFORE  
EXT 7B

## Describe Circumstance of the Accident

- We were driving on CTE (NORTH DIRECTION) before exit 7B, in heavy traffic conditions at approx. 2205 on 24 June 2023.
- We were driving on the left most lane.  
(A & B)
- Two cars were in front of us (refer diagram) and the cars in front of us.
- Car A suddenly braked, causing Car B to and our car, (car A) to brake as well.
- We managed to brake in time and there was no contact between Cars A, B & C (our car).  
our car & the car in front of us.
- However, the car behind us, Car B, (GB G5549X), was unable to stop in time and collided with the rear of our car (car C).

## Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NR12 ID card)





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Tang Kwai Sim	Cust No/Name LCV15740/Ms Tang Kwai Sim
103 Corporation Walk	Reg No/Reg Date SDQ3268M / 01/06/201
Singapore 618480	Date In/Mileage / 0
Contact No 97209008	Chassis No KNACC81CVH5079490
	Engine No G4LEHS212560
	Make/Model KIA/NIRO 1.6 A
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV15740	CRDVCH	30/06/2023/ 16:19		1015/ Vikneswaran Naidu A	15507
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW RR BUMPER, RR TAILGATE				3840.00
	REPAIR RR END PANEL, RR LH FENDER				1920
E PNT88000	REMOVE AND REFIT SENSOR				100.00
E PNT88000	RENEW REAR WINDSCREEN				380.00
E PNT88000	REMOVE AND REFIT TAILGATE TRIM AND MECHANISMS				220
E PNT98000	SPRAY REAR BUMPER, RR TAILGATE, RR END PANEL, REAR LH FENDER				1650
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00
A 10028901	CHECK WIRING AND ELECTRICAL				80
M SUNDRY	SEALING WINDSCREEN				80
M SUNDRY	SUPPLY SOLAR FILM TINT				280.00
M SUNDRY	ANTI RUST PROOFING				100
M SUNDRY	SUPPLY CNC BADGE				60
M SUNDRY	SUPPLY NUMBER PLATE bent				60
M SUNDRY	SUNDRIES				20
M COVER-RR BUMPER,UPR		1.00	615.00	00.00	615.00
M COVER-RR BUMPER LWR		1.00	392.00	00.00	392.00
M MOULDING ASSY-RR BUMPER SIDE, L		1.00	24.00	00.00	24.00
M REFLECTOR/REFLEX ASSY-RR LH		1.00	108.00	00.00	108.00
M COVER-RR BUMPER SIDE UNDER, LH		1.00	27.00	00.00	27.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Tang Kwai Sim	Cust No/Name LCV15740/Ms Tang Kwai Sim
103 Corporation Walk	Reg No/Reg Date SDQ3268M / 01/06/201
Singapore 618480	Date In/Mileage / 0
Contact No 97209008	Chassis No KNACC81CVH5079490
	Engine No G4LEHS212560
	Make/Model KIA/NIRO 1.6 A
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV15740	CRDVCH	30/06/2023/ 16:19		1015/ Vikneswaran Naidu A	15507
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BEAM-RR BUMPER		1.00	261.00	00.00	261.00
M BRACKET ASSY-RR BUMPER SIDE, LH		1.00	25.00	00.00	25.00
M PANEL ASSY-TAIL GATE		1.00	1478.00	00.00	1478.00
M GLASS ASSY-TAIL GATE		1.00	1179.00	00.00	1179.00
M PAD-WINDSHIELD GLASS		1.00	2.00	00.00	2.00
M EMBLEM-NIRO		1.00	25.00	00.00	25.00
M LOGO-KIA		1.00	42.00	00.00	42.00
M EMBLEM-ECO HYBRID		1.00	29.00	00.00	29.00
M LAMP ASSY-REAR COMB INSIDE, LH		1.00	636.00	00.00	636.00
M LAMP ASSY-REAR COMB OUTSIDE, LH		1.00	775.00	00.00	775.00
M LAMP ASSY-REAR COMB OUTSIDE, RH		1.00	775.00	00.00	775.00
M LAMP ASSY-REAR COMB INSIDE, RH		1.00	636.00	00.00	636.00
M BRACKET, IU ADHESIVE		1.00	26.00	00.00	26.00

SURVEYOR NAME: Rahul - Hg 9006068SURVEYOR SIGNATURE: [Signature]DATE: 11/07/23REMARKS: 6 daysRey b & paint

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

Nett 18,855.00  
8% GST on 18855.00 1508.40

Total Payable 20,363.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Surveyor : RASUL LKK  
Claim : TP EQ INSURANCE  
DOA : 24.06.2023  
Emailed : 29.07.2023  
Date Survey : 30.06.2023

VEHICLE NO : SDQ3268M  
MODEL : KIA/CERATO  
WIP : 15507

Material	:	\$	<u>4,277.00</u>
Labour	:	\$	<u>5,230.00</u>
Sub-Total	:	\$	<u>9,507.00</u>
	:	\$	<u>-</u>
Less Excess	:		
Total	:	\$	<u>9,507.00</u>
GST 8%	:	\$	<u>760.56</u>
Grand Total	:	\$	<u>10,267.56</u>
Finalise By/Date	:		<u>VIC/29.07.2023</u>

☒ REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 6 WORKING DAYS + 0 Days ( 0 ) Weekends  
+ 0 Days ( 0 ) Public Holiday  
TOTAL DAYS REPAIR TOOK = 6

☒ TP claim EQ INSURANCE

☐ Claim GIA / LTA fee                     

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others                     

☐ Third Party Report -

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Tang Kwai Sim  103 Corporation Walk Singapore 618480  Contact No Mobile: 97962626 11/07/2023	Cust No/Name LCV15740/Ms Tang Kwai Sim Reg No/Reg Date SDQ3268M / 01/06/2017 Date In/Mileage 11/07/2023/ 94822 Chassis/Package KNACC81CVH507949C /KC2R Engine No G4LEHS212560 Make/Model KIA/NIRO 1.6 A Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	29/07/2023/ 12:47	VIC	1015/ Vikneswaran Naidu A	15507		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER, RR TAILGATE REPAIR RR END PANEL,							1920.00
E PNT88000 REMOVE AND REFIT SENSOR							100.00
E PNT88000 RENEW REAR WINDSCREEN							380.00
E PNT88000 REMOVE AND REFIT TAILGATE TRIM AND MECHANICSM							220.00
E PNT98000 SPRAY REAR BUMPER, RR TAILGATE, RR END PANEL,							1650.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							280.00
A 10028901 CHECK WIRING AND ELECTRICAL							80.00
M SUNDRY SEALING WINDSCREEN							80.00
M SUNDRY ANTI RUST PROOFING							100.00
M SUNDRY SUPPLY CNC BADGE							60.00
M SUNDRY SUNDRIES							20.00
Z TEXT TP CLAIM EQ INSURANCE SURVEYOR: RASUL (LKK) DOA: 24.06.2023 06 REPAIR DAYS							
S SPECIALISTJOB TO SUPPLY REAR LICENSE PLATE WITH FRAME ( RECTANGULAR & BLACK)							60.00
S SPECIALISTJOB TO SUPPLY REAR WINDSCREEN SOLAR FILM (NIRO)							280.00
X COVER-RR BUMPER,UPR				1.00	615.00	00.00	615.00

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Tang Kwai Sim	Cust No/Name LCV15740/Ms Tang Kwai Sim
103 Corporation Walk	Reg No/Reg Date SDQ3268M / 01/06/2017
Singapore 618480	Date In/Mileage 11/07/2023/ 94822
Contact No Mobile: 97962626	Chassis/Package KNACC81CVH507949C /KC2R
11/07/2023	Engine No G4LEHS212560
	Make/Model KIA/NIRO 1.6 A
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	29/07/2023/ 12:47	VIC	1015/ Vikneswaran Naidu A	15507
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X COVER-RR BUMPER LWR		1.00	392.00	00.00	392.00
X MOULDING ASSY-RR BUMPER SIDE,L		1.00	24.00	00.00	24.00
X BEAM-RR BUMPER		1.00	261.00	00.00	261.00
X BRACKET ASSY-RR BUMPER SIDE,LH		1.00	25.00	00.00	25.00
X PANEL ASSY-TAIL GATE		1.00	1478.00	00.00	1478.00
X GLASS ASSY-TAIL GATE		1.00	1179.00	00.00	1179.00
X PAD-WINDSHIELD GLASS		1.00	2.00	00.00	2.00
X EMBLEM-NIRO		1.00	25.00	00.00	25.00
X LOGO-KIA		1.00	42.00	00.00	42.00
X EMBLEM-ECO HYBRID		1.00	29.00	00.00	29.00
X STAY-RR BUMPER LH		1.00	67.00	00.00	67.00
X SKID PLATE-RR BUMPER		1.00	122.00	00.00	122.00
X PIECE-RR BUMPER SIDE,LH		1.00	16.00	00.00	16.00

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts	4,277.00	Nett	9,507.00
Labour	4,630.00	8% GST on	760.56
Standard Menu	0.00		
Specialist Job	340.00	Total Payable	10,267.56
Diagnostics Job	0.00		
Sundry/Others	260.00		
Total(w/o GST)	9,507.00		

This is not an official tax invoice.  
This is a computer generated document, no signature is required.

Supp



**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 68661666



**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Tang Kwai Sim  103 Corporation Walk Singapore 618480  Contact No Mobile: 97962626 11/07/2023	Cust No/Name LCV15740/Ms Tang Kwai Sim Reg No/Reg Date SDQ3268M / 01/06/2017 Date In/Mileage 11/07/2023/ 94822 Chassis/Package KNACC81CVH507949C /KC2R Engine No G4LEHS212560 Make/Model KIA/NIRO 1.6 A Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	29/07/2023/ 12:46	VIC	1015/ Vikneswaran Naidu A	15507

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BEAM-RR BUMPER <del>RM</del> repeated	1.00	261.00	00.00	261.00
X STAY-RR BUMPER LH <del>LT</del>	1.00	67.00	00.00	67.00
X SKID PLATE-RR BUMPER <del>SW</del>	1.00	122.00	00.00	122.00
X PIECE-RR BUMPER SIDE, LH <del>SW</del>	1.00	16.00	00.00	16.00

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	466.00	Nett	466.00
Labour	0.00	8% GST on	37.28
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	503.28
Diagnostics Job	0.00		
Sundry/Others	0.00		
Total(w/o GST)	466.00		

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.