

REF: CS1/LAW23006754/vp3

Special Instruction:

L/SUM: 4,800 / REPAIR : 20 WORKING DAYS

ASSIGNMENT (Office)

From (Person): _____ of JusEquity Law Corporation Date/Time: 30/06/2023

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: C L APPRAISAL

Workshop: HL CYCLE PL

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FBP 4518P

Insured: GBJ 145P

at Workshop m/s HL CYCLE PL

Tel:

of 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883

Policy No:

Claim No: JEQ/210426/0721/HC-PDPI.ml

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29/06/2021

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red S ____ / ____ %; Original ____ days)

Date/Time: _____ Submit Final Fig _____, _____ days (Red \$ _____ / _____ %; Original _____ days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____