



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23006758/Kny3m4 Date: 19/07/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 8626G	Veh. Inspected	SDN 1111K	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10023271/SR	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	05/07/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES CLA180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD1173422N242120	Colour	METALLIC GREY	
Odometer	50091 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40R18	PIRELLI	8 mm	
L/H Front Tyre	225/40R18	PIRELLI	8 mm	
R/H Rear Tyre	225/40R18	PIRELLI	7 mm	
L/H Rear Tyre	225/40R18	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2023	Inspection Date	05/07/2023	
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	