

Service Request Details

Claim	S3M04NQ3
Reference	CS3/HSB23006787/Knp3m4 
Loss Date	26 June 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	28 Jun 2023 11:17:23 AM
Request Date	5 July 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information	
Incident	SMZ7782P
Vehicle	
Registration #	
Make	TPVD MERCEDES
Model	E200
Service Address	
, , ,	
Primary Contact/Insured	

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TEO Kitty

kitty.teo@axa.com.sg

Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 HSB-LKKInvoice-AC2304656.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2023
 Resurvey photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2023
 Resurvey photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2023
 SMZ 7782P-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2023
 REPLY FORM SOLICITOR.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	5 July 2023
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	4 July 2023
 SMZ7782P TP GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh	4 July 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
			Pandurang	
 SJ0G236R0003-SHD7165X.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	28 June 2023