

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TH / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SHA1073Hat Workshop m/s C DGE

of _____

Insured: SLK 2102B

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**GIA / PR Seen: _____ Consistent? : **Yes** or **No**Est. Repairs: _____ days Res.: **Yes** or **No**Lum Sum: _____ % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

PNR
Vehicle: **IN / OUT**Date: _____ Person Contacted: LTAEH236Veh No: SHA1073H Yr Regn: 26/08/19Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**Truck / Trailer or (a)Make: Hyundai AE 10NIQ c.c. 1580Colour: blue A/C: **Insured / Std / NI / NA**Sp.Reading: 499675 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: KMHIC851CVKU164283Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** orBrake: **Inorder / Jammed / Leaked / Burnt** orModi: NI / **S/Rim / STD A/Rim** orTyre Size: **F:** 195 / 65 R 15**R:** Deratun**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or MestlakeFrontR/Bal. 6 mmRearR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 04/07/23D.O.I. 6/7/23

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** oro/s frt.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : **Preli. Report**

1)

☐ : **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : **Site Insp (\$**☐ : **Interview (\$**☐ : **Tech. Invs (\$**☐ : **Weekend (\$**

Survey Fee: _____

Transportation: _____

____ S + RS ____ SI

Photos _____

Others _____

TOTAL _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: **SHA1073H**
Party At Fault: UNKNOWN

Ref. No:
Date of Loss: 04/07/2023
Driveable? YES

Make/Model: HYUNDAI IONIQ HYBRID, 1.6 GLS
DCT (A)
Vehicle Colour: BLUE
Engine No: G4LEKU297716
Odometer: 0 KM

Vehicle Reg. Date: 26/06/2019
Gen Condition: GOOD
Chassis No: KMHC851CVKU164283

Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair (day) 83

Not Authorised
6/7/23 @ 11.10am
H29009660P
mercusdmc@lkhauto.com

2/58

3 days Whaphu Heng -

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	2,437.08
Miscellaneous Items	11.00
Labour	1,970.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$) 4,418.08
+ GST 8.00% (S\$) 353.45
Nett Amount (S\$) 4,771.53

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Link Auto Consultants hence notify the Repairer of the following:

- To be in by before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Jul 2023)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA1073H/05/07/2023 15:08**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER RH <i>body</i>	20.00	0.00	*588.80 FL ✓
2	1		*FRT FENDER EMBLEM RH <i>RM</i>	20.00	0.00	*26.60 FL ✓
3	1		*FRT DOOR ASSY RH <i>body</i>	20.00	0.00	*1,797.20 FL ✓
4	1		*ROCKER PANEL GARNISH RH <i>de / to</i>	20.00	0.00	*290.00 FL ✓
5	1		*FRT DOOR COMFORT LOGO <i>RM</i>	0.00	0.00	*75.00 F ✓
6	1		*ADVERTISEMENT LOGO - FENDER <i>RM</i>	0.00	0.00	*100.00 F ✓
7	1		*ADVERTISEMENT LOGO - DOOR <i>RM</i>	0.00	0.00	*100.00 F ✓

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$) **2,977.60**- List Item Discount on L Items (\$\$) **540.52**Total Parts (\$\$) **2,437.08**

ComfortDelGro Engineering Pte Ltd/SHA1073H/05/07/2023 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	600 1,000.00
2	SPRAYPAINT	New	700 800.00
3	TUFF KOTE	New	30 50.00
4	TRANSFER DOOR PARTS	New	50 120.00
Gross Labour Cost (S\$)			1,970.00

ComfortDelGro Engineering Pte Ltd/SHA1073H/05/07/2023 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P-2702-6
202
2162-08
275
1380
3817-08
202
3052

Date/Time: 05.07.2023 14:45

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5902845

JC NO305559657

OMER
S COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO: SHA1073H	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 05.07.2023 11:15
YR OF MANU. 26.06.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU164283	COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 04.07.2023
ATURE: 3P.04.07.23

NO LABOR CODE DESCRIPTION



OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHA1073H

JU TOKIO

Vehicle No.:

SHA1073H

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard