

ASS. REC. BY:

REF: 21

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Optima

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 873k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLZ 24494 Yr Regn: 04, 18

Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf c.c. 999

Colour: M. L. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 51797 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAUZJW155179

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 5/7/23 D.O.I. 6/7/2023

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prel. Report

: Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

_____ S - RS. _____ SI

_____ P. _____

_____ Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Date : 05/07/2023
Vehicle No: SLZ2449Y
Model: VOLKSWAGEN GOLF TSI
Chassis: WVVZZZAUZJW155179-2017
Reg. Year: 2018
Policy No: D23MPCM000506
Date of Accident: 05/07/2023
Estimator: TING AN

TO MOTOR CLAIM DEPT
INDIA INT. INSURANCE PTE LTD
6 RAFFLES QUAY
#22-00 SINGAPORE 048580

Not Authorized
11 Pny @
Penney After Paint
Ex TBA *5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET	1		<i>Bu</i> \$900.00	✓
2	FRONT BONNET HINGE LH	1		<i>Diy</i> \$70.00	✓
3	FRONT BONNET HINGE RH	1		\$70.00	✓
4	FRONT BONNET STRUT LH	1		<i>Bu</i> \$80.00	X
5	FRONT BONNET STRUT RH	1		<i>Ju</i> \$80.00	X
6	FRONT BONNET LOCK	1		\$145.00	✓
7	FRONT BONNET INSULATOR	1		<i>Bu</i> \$215.00	X
8	FRONT GRILLE ASSY	1		<i>CM</i> \$280.00	✓
9	FRONT GRILLE EMBLEM	1		<i>CM</i> \$75.00	✓
10	FRONT AIR DUCT	1		\$45.00	✓
11	FRONT AIR DUCT TOP COVER	1		<i>CM</i> \$30.00	✓
12	FRONT HEADLAMP LH	1		<i>CM</i> \$410.00	✓
13	FRONT HEADLAMP RH	1		\$410.00	✓
14	FRONT HEADLAMP UPPER PANEL LH	1		<i>Bu</i> \$45.00	✓
15	FRONT HEADLAMP UPPER PANEL RH	1		<i>Bu</i> \$45.00	✓
16	FRONT BUMPER	1		<i>Bu</i> \$680.00	✓
17	FRONT BUMPER SIDE BRACKET LH	1		<i>Diy</i> \$40.00	✓
18	FRONT BUMPER SIDE BRACKET RH	1		<i>Bu</i> \$40.00	X
19	FRONT BUMPER LOWER GRILLE	1		<i>Net</i> \$145.00	✓
20	FRONT BUMPER SIDE GRILLE LH	1		<i>Net</i> \$50.00	✓
21	FRONT BUMPER REINFORCEMENT	1		\$410.00	✓
22	FRONT BUMPER ABSORBER FOAM	1		\$65.00	✓
23	FRONT SUPPORT PANEL	1		\$580.00	✓
24	FRONT SUPPORT BRACE PANEL	1		\$45.00	✓
25	FRONT A-PILLAR MOULDING LH	1		<i>Diy</i> \$40.00	✓
26	FRONT FENDER LH	1		REPAIR	
27	FRONT FENDER RH	1		REPAIR	
SUB TOTAL				\$4,995.00	
COST +10%				\$499.50	
PARTS TOTAL				\$5,494.50	

Date : 05/07/2023
 Vehicle No: SLZ2449Y
 Model: VOLKSWAGEN GOLF TSI
 Chassis: WVVZZZAUZJW155179-2017
 Reg.Year: 2018
 Policy No: D23MPCM000506
 Date of Accident: 05/07/2023

TO MOTOR CLAIM DEPT
 INDIA INT. INSURANCE PTE LTD
 6 RAFFLES QUAY
 #22-00 SINGAPORE 048580

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		<i>nn</i> \$40.00
2	FRONT BUMPER CLIPS	1		<i>mc</i> \$50.00
3	FRONT NUMBER PLATE & HOLDER	1		<i>BT</i> \$50.00
S/N TOTAL				\$140.00

X
✓
4511

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

600
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.

\$1,000.00 *800*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$120.00 *?*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$100.00 *200*

LABOUR TOTAL \$2,220.00

TOTAL \$7,854.50

TING AN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Branch (Motor Insurance Claims)

Signature: _____
Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Head office

6 Kung Chong Road Singapore 159143
Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel (+65) 6484 9919 | Fax (+65) 6481 1993



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/07/2023 10:49 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 05/07/2023 07:50 (SGT)
Exact Location of Accident PIE, Singapore
Additional Location Information PIE EXPRESSWAY (NEARBY EXIT 12), SINGAPORE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLZ2449Y

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner CHONG SENGIE
NRIC No SXXXX291H
Email Address SENGIEC@GMAIL.COM
Mobile Phone No (Phone) +65-92766236
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Golf
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 999

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Policy Number / Cover Note Number D23MPCM000506

DRIVER

Name of Driver CHONG SENGIE
NRIC No SXXXX291H
Date Of Birth 07/11/1992
Occupation Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 05/06/2023


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



PJE EXPRESSWAY

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	291H
Vehicle Details	
Vehicle No.:	SLZ2449Y
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jul 2023
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF TSI TL
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	CHZ644929
Chassis No.:	WVWZZZAUZJW155179
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$18,644.00
Original Registration Date:	26 Apr 2018
First Registration Date:	26 Apr 2018
Transfer Count:	2
Actual ARF Paid:	\$18,644.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2028
PARF Rebate Amount:	\$13,050.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,510.00
COE Rebate Amount:	\$18,495.00
Total Rebate Amount:	\$31,545.00

The information contained herein is correct as at 05 Jul 2023

OK