

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

: ALLIANZ INSURANCE SINGAPORE PTE LTD

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT23002008

Page

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

12 MARINA VIEW

Date

Qty

4. Jul 2023

#04-01, ASIA SQUARE TOWER 2

**Customer No.** Svc Advisor

: WZA011

SINGAPORE 018961

RUEBEN THOMAS

: SNA1564L

**Engine No** 

LEB81039611

Chassis No Model

ltem

Registration No

Customer

: JHMGR3830MS227666 : JAZZ H-LUXE E-CVT 21YM Date | Time **Surveyor Name**  4. Jul 2023 3:45:39 PM

Owner's Name

: LEE CHONG SHUN, GABRIEL

Amount

Ins Policy No.

**Survey Date Authorisation Date** 

Unit Price Disc %

8% GST

**Amount** 

**Amount** incld GST

Date of Accident

: 3/7/2023

Description

.

TP DIRECT SETTLEMENT (J/NO: ) OWNER: LEE CHONG SHUN, GABRIEL OWNER INSURER: TOKIO MARINE

ACC DATE: 03/07/2023

SURVEYED BY: DATE:

REF NO:

	REF NO:							
	TP INSURER: ALLIANZ INSURANCE							
	TP VEH: SLA700R							
				700.00	25	547.42	43.79	591.21
73211-TZA-E11	GLASS SET,RR.WINDSHIELD	1		729.90				
73225-TM8-000	RUBBER AWINDSHIELD DAM	2	2	3.90	25	5.85	0.47	6.32
73225-TZA-J01	RUBBER A,RR.WINDSHIELD	1	l	26.30	25	19.72	1.58	21.30
73226-TZA-J01	RUBBER B,RR.WINDSHIELD	1		32.30	25	24.22	1.94	26.16
73227-TZA-J01	RUBBER C,RR.WINDSHIELD	2	2	11.40	25	17.10	1.37	18.47
91502-TTA-003	CLIP,RR.WINDSHIELD LOWER	2	2	4.30	25	6.45	0.52	6.97
91502-TXA-J01	CLIP,RR.WINDSHIELD UPPER	2	2	2.90	25	4.35	0.35	4.70
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1		60.00		60.00	4.80	64.80
68100-TZA-E21ZZ	TAILGATE COMP	1	l	896.80	25	672.60	53.81	726.41
74895-TZA-003	GARNISH ASSY, TAILGATE LOWER	1	I	198.20	25	148.65	11.89	160.54
84431-TZA-J01ZA	LINING ASSY, TAILGATE LOWER	1	I	125.10	25	93.82	7.51	101.33
74440-TZA-003	WEATHERSTRIP, TAILGATE	1	I	66.70	25	50.02	4.00	54.02
74800-TKR-003	LOCK ASSY,TAILGATE	1	1	154.30	25	115.72	9.26	124.98
74870-TZA-013	STAY ASSY,L.TAILGATE OPEN	1	1	91.10	25	68.32	5.47	73.79
74820-TZA-013	STAY ASSY,R.TAILGATE OPEN	1	1	91.10	25	68.32	5.47	73.79
75701-TZA-J01	EMBLEM,H MARK BLU	1	1	19.80	25	14.85	1.19	16.04
90301-ST0-003	NUT,PUSH 3MM	2	2	2.10	25	3.15	0.25	3.40
75722-TZA-E01	EMBLEM,RR SET CAR	1	t	20.90	25	15.67	1.25	16.92
75723-TZA-J01	EMBLEM,RR.	1	1	50.10	25	37.57	3.01	40.58
	·							

#### Printed on 5/7/2023 9:24:09 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53,50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

: ALLIANZ INSURANCE SINGAPORE PTE LTD

For 24-hours Roadside Assistance, Call 98203838

: SQT23002008

Page

2

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

12 MARINA VIEW

#04-01, ASIA SQUARE TOWER 2

SINGAPORE 018961

Registration No : SNA1564L

Chassis No

: JHMGR3830MS227666

Model Owner's Name

: JAZZ H-LUXE E-CVT 21YM

Ins Policy No. Date of Accident

:

: LEE CHONG SHUN, GABRIEL

: 3/7/2023

Document No.

: 4. Jul 2023 Date : WZA011 Customer No.

: RUEBEN THOMAS Svc Advisor

: LEB81039611 **Engine No** : 4. Jul 2023 3:45:39 PM Date | Time

**Surveyor Name** 

**Survey Date** 

**Authorisation Date** 

bate of Accident	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
1tem 34155-TZA-J01	LIGHT ASSY,L.LID	1	354.60	25	265.95	21.28	287.23
34150-TZA-J01	LIGHT ASSY,R.LID	1	354.60	25	265.95	21.28	287.23
33550-TZA-J01	TAILLIGHT ASSY,L.	1	373.30	25	279.97	22.40	302.37
33500-TZA-J01	TAILLIGHT ASSY,R.	1	373.30	25	279.97	22.40	302.37
04715-TZA-000ZZ	FACE,RR.BUMPER	1	421.00	25	315.75	25.26	341.01
91505-TM8-003	CLIP,BUMPER	2	2.30	25	3.45	0.28	3.73
33555-TZA-J01	REFLECTOR ASSY,L.RR.	1	40.50	25	30.37	2.43	32.80
33505-TZA-J01	REFLECTOR ASSY,R.RR.	1	40.50	25	30.37	2.43	32.80
71680-TZA-003	SPACER,L.RR.BUMPER SIDE	1	18.70	25	14.02	1.12	15.14
71630-TZA-003	SPACER,R.RR.BUMPER SIDE	1	18.70	25	14.02	1.12	15.14
71585-TZA-000ZZ	EXTN COMP,L.RR.BUMPER	1	19.80	25	14.85	1.19	16.04
71535-TZA-000ZZ	EXTN COMP,R.RR.BUMPER	1	19.80	25	14.85	1.19	16.04
NMRS-4P-JAZ21	REAR SENSOR 4P RS886	1	320.00		320.00	25.60	345.60
NMRS-CABLE-JAZ21	REAR SENSORS CABLE	1	130.00		130.00	10.40	140.40
74940-T00-Z01	BUZZER ASSY,SMART	1	19.40	25	14.55	1.16	15.71
76700-TZA-J01	MOTOR ASSY,RR.WINDSHIELD WIPER	1	246.10	25	184.57	14.77	199.34
76720-TZA-J01	ARM,RR.WIPER	1	43.20	25	32.40	2.59	34.99
76730-TZA-J01	BLADE,RR.WINDSHIELD WIPER 300MM	1	35.40	25	26.55	2.12	28.67
84640-TZB-J01ZA	LINING,RR.PANEL	1	41.70	25	31.27	2.50	33.77
84651-TZB-T81ZA	LINING ASSY,L.TRUNK SIDE	1	269.90	25	202.42	16.19	218.61
84521-TZB-G31ZA	LID ASSY,SPARE TIRE	1	231.10	25	173.32	13.87	187.19
84641-TZB-J02ZA	BOX ASSY,TRUNK UNDER	1	104.30	25	78.22	6.26	84.48
84400-TZB-G01ZA	COVER ASSY,RR.PARCEL	1	360.80	25	270.60	21.65	292.25
66100-TZC-305ZZ	PANEL COMP.RR	1	368.00	25	276.00	22.08	298.08
04655-TZB-300ZZ	PANEL SET,RR.FLOOR	1	803.00	25	602.25		650.43
65590-TZB-T00ZZ	STIFFENER COMP,L.RR.	1	102.30	25	76.72		82.86
72841-SH3-315	OILSHEET	1	43.50	25	32.62		35.23
NMDVR-VUEROID-2C	DVR, VUEROID 2 CHANNEL	1	343.93		343.93		371.44
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.60	48.60

#### Printed on 5/7/2023 9:24:09 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000,00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

: ALLIANZ INSURANCE SINGAPORE PTE LTD

For 24-hours Roadside Assistance, Call 98203838

Document No.

Customer No.

: SQT23002008

Page 3

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

12 MARINA VIEW

#04-01, ASIA SQUARE TOWER 2

SINGAPORE 018961

: JHMGR3830MS227666

: JAZZ H-LUXE E-CVT 21YM

: LEE CHONG SHUN, GABRIEL

Svc Advisor

Date

: WZA011

: 4. Jul 2023

: RUEBEN THOMAS

**Engine No** 

: LEB81039611

Date | Time

4. Jul 2023 3:45:39 PM

**Surveyor Name** 

**Survey Date** 

Authorisation Date

Ins Policy No. **Date of Accident** 

**Registration No** 

Owner's Name

Chassis No

Model

.

: 3/7/2023

: SNA1564L

M	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
ltem	Description			Sum Item	6343.74	507.54	6,851.28
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00		300.00	24.00	324.00
	, , , , , , , , , , , , , , , , , , ,		Sum Ex	t. Service	300.00	24.00	324.00
BOSUN	SUNDRIES	1	50.00		50.00	4.00	54.00
BML02l	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	14.40	194.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00		200.00	16.00	216.00
BOJSE	BODY JOINT SEALANT.	1	200.00		200.00	16.00	216.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	8.00	108.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	20.00	270.00
BMU30R	REMOVE & INSTALL RR EXHAUST SYSTEM.(N)	1	450.00		450.00	36.00	486.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	36.00	486.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	36.00	486.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	36.00	486.00
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	450.00		450.00	36.00	486.00
BC01R	REMOVE & RENEW IN-CAR DASH CAM	1	450.00		450.00	36.00	486.00
BML11R	REMOVE, INSTALL HYBRID BATTERY & RESET SYSTEM	<i>I</i> 1	450.00		450.00	36.00	486.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	52.00	702.00
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	650.00		650.00	52.00	702.00
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	5400.00		5400.00	432.00	5832.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	<sup>S.</sup> 1	3200.00		3200.00	256.00	3456.00
			•	Sum Labor	14680.00	1,174.40	15,854.40

Survey By

Printed on 5/7/2023 9:24:09 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

**Registration No** 

Owner's Name

Ins Policy No.

**Date of Accident** 

**Chassis No** 

Model

Website: www.honda.com.sg

: ALLIANZ INSURANCE SINGAPORE PTE LTD

For 24-hours Roadside Assistance, Call 98203838

Document No.

Customer No.

: SQT23002008

: 4. Jul 2023

Page

4

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

12 MARINA VIEW

#04-01, ASIA SQUARE TOWER 2

SINGAPORE 018961

: JHMGR3830MS227666

: JAZZ H-LUXE E-CVT 21YM : LEE CHONG SHUN, GABRIEL

Date

: WZA011 : RUEBEN THOMAS

Svc Advisor **Engine No** 

: LEB81039611

Date | Time

: 4. Jul 2023 3:45:39 PM

**Surveyor Name** 

**Survey Date** 

**Authorisation Date** 

**8% GST Amount** 

**Amount** incld GST

Date & Time

Description

: 3/7/2023

: SNA1564L

Unit Price Disc %

Total Amount 21,323.74 1,705.94

Amount

23,029.68

Excess

Status

Signature

Total (Inclusive of GST)

23,029.68

Printed on 5/7/2023 9:24:09 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



# SINGAPORE ACCIDENT STATEMENT

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 04/07/2023 16:35 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 03/07/2023 18:35 (SGT) Exact Location of Accident Near 2001 ECP, Singapore 489675 Additional Location Information ECP TOWARDS CITY (L/POST 152) Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SNA1564L

#### INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LEE CHONG SHUN, GABRIEL NRIC No SXXXX013I Email Address gabriel.alphonsus@gmail.com Mobile Phone No (Phone) +65-90239007 Alternative Phone No

#### VEHICLE PARTICULARS

Manufacturer Honda Model Jazz Variant E-HEV Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party vour vehicle? Vehicle Category Private car Auto CC 1500

#### INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd Policy Number / Cover Note Number MQ002381

#### DRIVER

Name of Driver LEE CHONG SHUN, GABRIEL NRIC No SXXXX013I 18/10/1986 Date Of Birth Occupation Indoor

Date Of Driving Pass 21/08/2009 Driving experience 13 YEARS AND 11 MONTHS Gender Male Mobile Number (Phone) +65-90239007 Alt. Phone Number Email Address gabriel.alphonsus@gmail.com Address **BLK 648B TAMPINES STREET 62** Address complement #08-149 Postcode 522648 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? Nο Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Yes Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name KANG TYNG NATASHA Gender **Female** PASSENGER 2 Name ATHENA ZIPPORAH LEE Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name Changi Neighbourhood Police Centre Police Station Phone No (Phone) +65-18005872999 Alt. Police Station Phone No (Fax) +65-65872900 Police Station Address 9 Simei Street 2 Singapore 529914 Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED POLICE REPORT ATTACHMENT(S) Are accident photos available for attachment? Yes

Yes

Was there any video captured by Car Camera?

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA700R
Vehicle Manufacturer	Toyota
Vehicle Model	Vellfire
Vehicle Variant	
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	ALFAN FADHLAN
Contact Number	(Phone) +65-83883525
Address	41315-4305
Address complement	BHAPPIPTING S
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	HAMADA BARANA
No. Of Passenger (Including Driver)	

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMP1714D
Vehicle Manufacturer	Kia
Vehicle Model	*
Vehicle Variant	#
Vehicle Colour	**
Vehicle Category	Private car
Name of Driver	<u>u</u>
Contact Number	¥
Address	`#
Address complement	*
Postcode	75
Insurance Company Name	.77
Nature Of Damage	9
Details of property damaged in accident	$\underline{a}$
No. Of Passenger (Including Driver)	¥

## DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SMR4438X
Vehicle Manufacturer	Honda
Vehicle Model	<b>5</b>
Vehicle Variant	¥
Vehicle Colour	*
Vehicle Category	Private car
Name of Driver	
Contact Number	<del>-</del>
Address	<u>-</u>
Address complement	4
Postcode	-
Insurance Company Name	#
Nature Of Damage	**
Details of property damaged in accident	豪
No. Of Passenger (Including Driver)	<u></u>

## DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number Vehicle Manufacturer	SHD487M Renault
Vehicle Model	2
Vehicle Variant	4
Vehicle Colour	Red
Vehicle Category	Taxi

Name of Driver	-
Contact Number	20
Address	-
Address complement	-
Postcode	:=0
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	-

## DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number Vehicle Manufacturer Vehicle Model	SLE2101K Volkswagen Jetta
Vehicle Variant	<b>32</b> 0
Vehicle Colour	Gray
Vehicle Category	Private car
Name of Driver	
Contact Number	
Address	-
Address complement	*
Postcode	<u>≅</u> /1
Insurance Company Name	(20)
Nature Of Damage	940
Details of property damaged in accident	H-1
No. Of Passenger (Including Driver)	<b>3</b> 33

## DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number Vehicle Manufacturer Vehicle Model	SNB1313P BMW
Vehicle Variant	200
Vehicle Colour	Blue
Vehicle Category	Private car
Name of Driver	·
Contact Number	500
Address	( <del>40</del> )
Address complement	3 <del>7</del> 7
Postcode against the second and the	
Insurance Company Name	<b>€</b> /
Nature Of Damage	20
Details of property damaged in accident	20
No. Of Passenger (Including Driver)	(#0)

## INJURED PERSONS DETAILS

## INJURED 1

Name of injured person Gender	KANG TYNG NATASHA Female
Phone No	<b>2</b> 1
Address	BLK 648B TAMPINES ST 62
Address Complement	#08-149
Post Code	522648
Approximate Age Years Old	₹.
Injuries Sustained	RIGHT CHEEK SWOLLEN
Injured person in which vehicle?	SNA1564L
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

Vehicle Number: SNA 1564 L

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate unity liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being anade available afore aid.
- 8. Consent under the Personal Data Protection Act (PDPA) Funderstand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all marger(s) who have in used vehiclo(s) involved in this accident (all insurer(s) who have insured vehicle[s] involved in this accident shall be collectively referred to as the "insurers"), the insurers lawyers law lims, the Monetary Authority of Singapore and any relevent government agency fauthority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing handling and/or dealing with my claims (called lively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes;
  - (c) My Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for non-or more of the above Purposes.
  - my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, (d) investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

fill for complying with requirements under any regulations, laws or court orders.

4 July 2023

Draver's Synature (If dower is not the policyhelder)

Reporting Centre Personnel's Signature Name

MRIC/FAN Nov:

4

				SKETCH PLAN
	EXIT COR		AURENEMA AURENEMA	A: SNA 1564 L 3: SLA 700 R : SMP 1714 D : SME 4438 X SUD 487 M SCE 2101 K SNB 1313 P
DESCRIBE CIRCUMS	ANCES OF THE ACCIDENT	THILL	180	P TOWARDS CMY
Reter	to attaches poli	ce repor	+ -	
DECLARATION				
	atticulius are frue in évery respect.		EU	eut.





Police Station Of Origin: Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No: 1800-5872999

1 of 4 Report No. T/20230704/2005

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/07/2023 00:21			Vide Report No.: G/20230703/0135	Station Diary No.:		
Informant	's Particu	lars				
Name of Informant: LEE CHONG SHUN, GABRIEL			Address: APT BLK 648B TAMPINES STREET 62 #08-149 SINGAPORE 522648			
ID Type / ID No.: NRIC NO / S8631013I Nationality: SINGAPORE CITIZEN			Contact No.: Home/Office: Mobile: 90239007 Email:			
Sex: Age: Date of Birth: Male 36 18/10/1986		Date of Birth: 18/10/1986	Type of Informant: Driver			
Race: Chinese			Language:			
Occupation: Business Development			Driving Licence Information Class: 2B,2A,2,3	: Date of Expiry:		

General Inform	nation of the Accident			Section and the section of the secti			
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 03/07/2023 18:35	Type of Location: Straight Road			
Location:							
EAST COAST	PARKWAY						
Weather:		Road Surface:					
Raining		Wet	Wet				
Traffic Flow:		Traffic Control:		Traffic Volume:			
One Way		Not Controlled	rolled Heavy				
Type of Collision			nyone conveyed by				
Between Moving Vehicles - Head To Rear				mbulance:			
			Ye	es			

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SDP2662U	Car	(8)			Slightly Damaged	0
SHD487M	Car		+01	55	Slightly Damaged	2
SLA700R	Car				Slightly Damaged	0
SLE2101K	Car		124		Slightly Damaged	0





T/20230704/2005

2 of 4

Report No. T/20230704/2005

Police Station Of Origin: Changi N.P.C 9 Simei Street 2 SINGAPORE 529914 Tel No: 1800-5872999

### **CONTINUATION OF REPORT**

Details of V	ehicle Invo	lved				
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMP1714D	Car				Slightly Damaged	0
SMR4438X	Car				Slightly Damaged	1
SNA1564L	Car	HONDA	JAZZ 1.5 H- LUXE ECVT	Blue	Seriously Damaged	2
SNB1313P	Car				Slightly Damaged	0

Details of Vo	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SNA1564L	TOKIO MARINE INSURANCE	MQ002381	07/06/2021	06/06/2025
	SINGAPORE LTD.			

Details of Perso	on Involved					
Any Pedestrian I	nvolved: No		·			
No. of Pedestrian	ns Injured: NIL		Use of Peo	destriar	Cross	sing: NA
Passenger						
Name	ATHENA ZIPPORAH	LEE	ID No.		•	T2111329D
Related Vehicle	SNA1564L (Car)	1	Contact No.		NIL	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL	
Date Treatment	NIL		Date Discharge   NIL			
No. of Days gran	ted Medical Leave	NIL	Degree of Injury NIL			
Driver						
Name	LEE CHONG SHUN,	GABRIEL		ID No		S8631013I
Related Vehicle	SNA1564L (Car)		Contact No.		90239007	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: 2B,2A,2,3 Date of Expiry: NIL	
Date Treatment NIL			Date Discharge NIL			
No. of Days granted Medical Leave NIL			Degree of Injury NIL			





020070472000

3 of 4

Report No. T/20230704/2005

Police Station Of Origin: Changi N.P.C 9 Simei Street 2 SINGAPORE 529914 Tel No: 1800-5872999

#### **CONTINUATION OF REPORT**

Passenger			a Marina	19 19 19 1		
Name	KANG TYNG NATASHA			ID No		S9030968D
Related Vehicle	SNA1564L (Car)			Contact No.		97847426
Hospital/Clinic	ONECARE CLINIC UBI			Class Drivin Licend Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	03/07/2023	Date Discl	narge	03/07	//2023	
No. of Days gran	03	Degree of		NIL		

### **Brief Details.**

On the above-mentioned date time and location, I was driving my vehicle(SNA1564L) in the lane 1 of the expressway driving at around 70km/hr. At that point of time, it was raining, and the traffic was heavy, the traffic in front of me slowed down and gradually came to a stop and I also slow down and came to a stop. Suddenly, I heard a loud bang from a few vehicles back and next moment the car behind me (SLA700R) had hit the back of my car.

I got out of my vehicle and saw a chain collision of 7 cars with another vehicle SDP26625U with a slight dent on his right front bumper parked beside the vehicle behind me (SLA700R).

I made a check on everyone involved and subsequently called for police assistance vide

G/20230703/0135. I then saw and the driver of the vehicle (SDP2662U) saying something along "Since there's no injuries" and then went back into his vehicle and drove off. I did not manage to establish his particulars and I only have picture of his vehicle.

I am not fully aware of the injuries sustained by the people in the other vehicles.

The ambulance arrived shortly after and conveyed both my daughter and wife to KK hospital conscious. There were damages to all vehicles involved and the damages on my vehicle are major dent on the back of my car as well as scattered windows.

I manage to exchange particulars with drivers from vehicle SLA700R, SMP1714D, SMR4438X and that is when the Traffic Police came and took over the scene. I then handed over my Micro SD card to the Traffic Police officer who attended to me.



Police Station Of Origin: Changi N.P.C 9 Simei Street 2 SINGAPORE 529914 Tel No: 1800-5872999

NP168



T/20230704/2005

4 of 4

Report No. T/20230704/2005

**CONTINUATION OF REPORT** 

Signature of Officer Recording The Report:	Signature Of Informant:
SGT 2 ALAN KWAN YI HUI	- July
Signature Of Interpreter:	Date/Time:
Not applicable	04/07/2023 00:21
	E (40)
Officer In Charge Of Case:	Classification Of Case:
TP/GIT/	
SGT 3 MUHAMMAD SYAKIR BIN ADANAN Contact No.: 65476236	
CONIACI, 190., 0047 0230	E .