





ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP (CT)

Vehicle No. : SLD5877R

Make & Model : HONDA ODYSSEY

Year of Manufacture : 2016

Chassis No. : JHMRC1890GC203714

Ins Company : III

Engine No. : K24W72011792

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 21.06.2023

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimates**

Case Owner : KELVIN

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 2,398.00

Plus/Less 20% \$ 479.60

Total of Cost / List \$ 1,918.40

(b) Nett Price Items \_\_\_\_\_

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 1,918.40

Labour (Appendix B) \$ 810.00

Total Repair Cost \$ 2,728.40

**Operation**

KELVIN SU TEL:97864236 E:kelvinsukwen@cdge.com.sg  
JOHARI TEL:97213705 E:joharibh@sparkcarcare.com  
OI SUN PIN TEL: 97288916 E:oisunpin@cdge.com.sg  
SOO LEONG KEAT TEL:98328740 E:soolk@cdge.com.sg

*Not Authorized  
21/6/23 @  
Pulvinny After Rain*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKIC  
Survey conducted on : 7/7/23 at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : le Date: 7/7/23

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SLD5877R Case Owner : KELVIN

Make & Model : HONDA ODYSSEY Manufacture : 2016

Chassis No : JHMRC1890GC203714 Engine No : K24W72011792

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : KELVIN Type of Claim : TP (CT)

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1	<i>Bu/nd</i>	\$ 720.00			<input checked="" type="checkbox"/>
2	REAR BUMPER RETAINER -LH	1	<i>pu</i>	\$ 55.00			<input checked="" type="checkbox"/>
3	LHR CORNER PANEL	1	<i>n</i>	\$ 165.00			<input checked="" type="checkbox"/>
4	LHR TAILLAMP (OUTER)	1	<i>cm</i>	\$ 821.50			<input checked="" type="checkbox"/>
5	LHR TAILLAMP (INNER)	1	<i>pu</i>	\$ 421.50			<input checked="" type="checkbox"/>
6	REVERSE SENSOR	1	<i>pu</i>	\$ 160.00			<input checked="" type="checkbox"/>
7	REAR BUMPER CLIPS	10	<i>pu</i>	\$ 55.00			<input checked="" type="checkbox"/>
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 22/06/2023 12:22 (SGT)  
Reported by ..... Both Policyholder and Actual Driver  
Date of Accident ..... 21/06/2023 14:00 (SGT)  
Exact Location of Accident ..... Woodleigh Park, Singapore  
Additional Location Information ..... WOODLEIGH MALL BASEMENT CARPARK  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLD5877R

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... WAYNE CHUNG HON MUN  
NRIC No ..... SXXXX455D  
Email Address ..... gerawayne@gmail.com  
Mobile Phone No ..... (Phone) +65-94555922  
Alternative Phone No ..... -

### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Odyssey  
Variant ..... MPV  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 2400

### INSURANCE COMPANY

Name of Insurance Company ..... MSIG Insurance (Singapore) Pte. Ltd.  
Policy Number / Cover Note Number ..... A 300608887 QMY

### DRIVER

Name of Driver ..... WAYNE CHUNG HON MUN  
NRIC No ..... SXXXX455D  
Date Of Birth ..... 13/11/1976  
Occupation ..... Indoor

