

ASS. REC. BY:

REF: C12/23006862/Kgp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Com Del

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCV 2455A Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis C.C. 1598

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: 83326 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: NR053RE14804575434

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Davanti

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 14/3/23

Survey held at _____

Rear

R/Bal. 4 mm

L/Bal. 4 mm

D.O.I. 7/7/2023

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/7 1100h @ 1100h Cash used @ 882,45%

Date/Time, File Pass to?

: Prell. Report

: Final Report

1) 25/7 1100h

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trlp: 1

Survey Fee:

Transportation

S + RS. SI

Fixt. Ins

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format: EZ Claims

Lump Sum / I.B.F. (\$) 1100



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SLV2455A

Make & Model : TOYOTA COROLLA ALTIS

Year of Manufacture : 2017

Chassis No. : _____

Ins Company : CHINATAIPING INSURANCE

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 14/03/2023

Time of Accident : _____

Suggested Days of Repair : 4 DAYS

In-house Vehicle Assessor : _____

Repair Estimates

Parts (a) Cost / List Price Items \$ 980.00

Plus/Less 10% \$ 98.00

Total of Cost / List \$ 882.00

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 50.00

Total Parts Cost (Appendix A) \$ 932.00

Labour (Appendix B) \$ 1,050.00

Total Repair Cost \$ 1,982.00

The above total will be subjected to 8% G.S.T.

Case Owner : _____

Signature : _____

Contact No
Operation
KELVIN SU
TEL: 9786 4236
E: kelvinsukwen@cdge.com.sg

JOHARI
TEL: 972103705
E: joharibh@sparkcarcare.com

SUN PIN
TEL: 9728 8916
E: oisunpin@cdge.com.sg

*Not Authorized
Phenny Blegain
11 Ramp @ 1100hrs*

Name of Surveyor : Kenneth

Company : CLC

Survey conducted on : 7/7/23 at _____

Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : He Date: 7/7/23

Spark Car Care

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SLV2455A Case Owner : 0

Make & Model : TOYOTA COROLLA ALTIS Year Manufacture : 2017

Chassis No : 0 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER <i>556-40</i>	1	<i>But New</i>	\$ 754.00			✓
2	REAR BUMPER RH REFLECTOR	1	<i>CM</i>	\$ 77.00			✓
3	REAR BUMPER RH RETAINER <i>109.30</i>	1	<i>D's</i>	\$ 149.00			✓
4	REAR BUMPER CLIPS	1	<i>h</i>			\$ 50.00	✓
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	775H
Vehicle Details	
Vehicle No.:	SLV2455A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS ELEGANCE AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	1ZR0A34130
Chassis No.:	MR053REH604575434
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,690.00
Original Registration Date:	27 Dec 2017
First Registration Date:	27 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$22,366.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2027
PARF Rebate Amount:	\$15,656.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$16,200.00
Total Rebate Amount:	\$31,856.00

The information contained herein is correct as at 26 Jun 2023

OK