Kenneth	
	ASSIGNMENT
From: Date:	Veh No: SLE 4800 Yr Regn: 121 20
Estimated Cost:	Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
is inspect vehicle No:	Makes Da 0 (A)
at Workshop m/s Alan'i	
Of	STATE OF MICE NO. INSURED STATE IN
Insured:	Sp. Keading 4/694 T/Radio: Insured / Std / N1 / NA Eng/No:
Policy No.	
Claims No.	C/No: WBAGV22040CF 31550 Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: 2	Steering: Inorder / Jammed / Leaked / Burnt or
(Cflent's Record)	- Coaked / Bumt of
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or Mod : Nil /8/Rim STD A/Rim or
	— OTO AKIIII OF
(Policy Condition)	
Remark: The veh had commenced its N/S C	R: 275/307R20
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value: § 175/C	Ernel
IDAC Accident Rport: Consistent? : Yes or No	D/Day D
GIA / PR Seen: Consistent?: Yes or No	mm N/8a/. 0 mm
Est. Repairs: Od days Res.: Yes or No	mm Usal, inm
Lum Sum: 20 % 3 Val.: Yes or No	D.O.A. 30/6/23 D.O.I. 7/7/20. Survey held at
CA / REV / REP. / 24 HRS Date:Person Contacted: Vehicle: IN / O	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
	transfer of the second of the
	The state of the s
ato/Time, File Pass to? Prell. Report	Days Of Repair:
: Final Report	
la/lime, File Return to?	Resurvey No. of Trip: Survey Fee:
	Transportation
Add Fee	9: Site Insp (\$) _ s - RSSI
•	Internation (C
ort Format :	
	Tech Invs (\$). Others
Sum / I.B.I: (\$	Weekend (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7. Sin Ming Industrial Estate, #01-76, Singapore 575642. Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N GST Reg. No.: 201113667N

Your Reference : DMPCSNW00268622202

Accident Date : 30-Jun-2023

Our Ref : 023140 / CHAN

CHINA TAIPING INSURANCE (SINGAPORE) P/L

3 ANSON ROAD

#16-00

SPRINGLEAF TOWER Singapore 079909 No.: 06869

Date: 04-Jul-2023

PAGE: 1

NOT Nothankel

Ully & Merry After Paint

ESTIMATED COST OF REPAIR FOR BMW 8401 GRAN COUPE SLE480D

1 pc Front n/s fender	1,850.00
1 pc Front n/s fender air vent	ner 140.00
1 pc Frt n/s fender inner shield(F	180.00 x
1 pc Frt n/s fender inner shield(R	230.00 7
1 pc Front n/s door	R 2,900.00
1 pc Front n/s door rubber	nc 330.00 —
1 pc Front n/s door rubber-outer	Na 95.00 7
1 pc Front n/s door rubber-inner	Ma 380.00 7
1 pc Front n/s door handle seal	55.00 X
1 pc Rear n/s door	4 2,900.00
2 pcs Rear n/s door hinge	@ S\$105.00 210.00 X
1 pc Rear n/s door rubber	New 330.00
1 pc Rear n/s door rubber -front	n 145.00 —
1 pc Rear n/s door rubber -outer	ne 420.00
1 pc Rear n/s door rubber -inner	m 280.00
1 pc Rear n/s door handle seal	™ 55.00 X
1 pc Front n/s shock absorber	2,200.00 7
1 pc Front n/s knuckle arm	1,000.00 7
1 pc Front n/s knuckel bearing hub	580.00 7
	480.00 7
	600.00 7
1 pc Front n/s top arm	260.00 X
pc Front n/s ABS sensor	1,850.00 X
pc Rear shock absorber	780.00 7
pc Rear n/s knuckle arm	
pc Rear n/s knuckle bearing hub	700.00 7
pc Rear n/s lower arm	380.00 7
pc Rear n/s top arm	550.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642. Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N GST Reg. No.: 201113667N

Page: 2

Your Reference : DMPCSNW00268622202

1 pc Rear n/s training arm 650.00 7 1 pc Rear n/s ABS sensor 250.00 7

20,780.00 2,078.00 Add: 10%:

Orginal on only 22,858.00 M 3,000.00 sn 2 pcs N/s front & rear sport rim @ \$1500.00 Ma 60.00 sn L 1 pc Front & rear door rivet (set)

To dismantle and lower front 250.00 7 undercarriage

To dismantle and lower rear 250.00 7

80.00 To check and adjust wheel alignment

1,600.00 /320/ To putty and spray replaced parts

To remove, cut-out damaged parts, panel beating, welding, align, 1,200.00 9001

120.00 To transfer two left side rim

S\$29,418.00 Total:

=========

Singapore Dollars Twenty Nine Thousand Four Hundred and Eighteen Only

undercarriage

refix and to renew above parts

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	424F
Vehicle Details	
Vehicle No.:	SLE480D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Jul 2023
Vehicle Make:	B.M.W.
Vehicle Model:	840I GRAN COUPE
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	12886169B58B30C
Chassis No.:	WBAGV22040CF31550
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$103,862.00
Original Registration Date:	03 Dec 2020
First Registration Date:	03 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$158,952.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Dec 2030
PARF Rebate Amount:	\$119,214.00
Intended COE Rebate Details	
COE Expiry Date:	02 Dec 2030
COE Category:	E - Open - all except motorcycle
	10
COE Period(Years):	\$41,503.00
QP Paid:	\$30,425.00
COE Rebate Amount:	\$149,639.00
otal Rebate Amount:	A STATE OF THE PARTY OF THE PAR

The information contained herein is correct as at 07 Jul 2023

10236U0004 / Vin's Motor Pte Ltd [575722]
NTRY DATE & TIME: 30/06/2023 16:31 (SGT)
SUBMITTED BY: YEE SHU4-YAW VERSION: 1 (30/06/2023 16:31 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withouting of material 1000 mission of policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/06/2023 16:31 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 30/06/2023 08:05 (SGT) t Location of Accident Singapore Additional Location Information WOODLEIGH LANE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

SLE480D

INSURED/POLICYHOLDER Is company? Name Of Registered Owner SHANGGUAN WEIQUAN SXXXX424F NRIC No WEIQUAN@QUANFENG.COM.SG Email Address (Phone) +65-91195098 Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Vehicle Registration Number

BMW Manufacturer 840I GRAN COUPE Model Variant Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to Yes your vehicle? Vehicle Category Private car **Transmission** Auto 2998 CC

INSURANCE COMPANY

China Taiping Insurance (Singapore) Pte. Ltd. Name of Insurance Company DMPCSNW00268622202 Policy Number / Cover Note Number

DRIVER

SHANGGUAN WEIQUAN Name of Driver SXXXX424F NRIC No 08/05/1993 Date Of Birth Indoor Occupation

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
 report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my daims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, maylare permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Furnises.

Cultar 30 / 23

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Withessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan