

# N-51 AUTOMOTIVE PTE LTD

**Company & GST Registration No. 200616038C**

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

**SKP 5726 S**

Your ref:

**SLU 9699 Y**

07 July 2023

## **INDIA INTERNATIONAL INSURANCE PTE LTD**

64 CECIL STREET

#04-00 & #05-00 IOB BUILDING

SINGAPORE 049711

Attn: Motor Claims Department

Dear Sir/Madam,

**NAME OF CLAIMANT : NISSANKA NISSANKAGE INDRANI MANGALIKA WIJESOORIYA**

**VEHICLE NUMBER : SKP 5726 S**

**YOUR INSURED VEHICLE NUMBER : SLU 9699 Y**

**ACCIDENT ON 03 JULY 2023 AT ABOUT 06:40 HOURS**

**ALONG WOODLANDS CENTRE RD TWDS AVE 1 RIGHT TURN ONTO AVE 3**

We refer to your email/fax dated **07 July 2023** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

### **N-51 AUTOMOTIVE PTE LTD**

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-18

Singapore 417921

Contact Person:

**6842 0051 / 6744 0510 (Melody)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



**N-51 AUTOMOTIVE PTE LTD**



**bizSAFE**

#### **FOR SURVEYOR:**

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: