



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2023

User ID : GohKK2

Section A - Accident Details			
Registration Number	SMB158P		
Case Reference Number	BUS/07/23/7009		
Registration Date	21/10/2011		
Company Type	SMRT Buses Ltd		
Make	MERCEDES		
Model	CITARO O530		
Name of Driver	Zhou Xiaoyong		
Type of Accident	Side Swipe		
Accident Date and Time	7/7/2023 11:00 AM		
Accident Reported Date and Time	7/7/2023 2:20 PM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC,if any	SMB158P - FRONT PORTION GBG5890D (TP) - INSURED WITH INCOME		
Prepared Date and Time	10/7/2023 10:41 AM		
Chassis Number	WEB62808323122697		
Mileage			
Work Shop			
Repair Completion Date and Time			

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$6,834.94	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$9,940.94	\$0.00
Lump Sum Total	\$9,950.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	10/07/2023 10:55 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2023

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00						
Total Labour			\$2,120.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00						
Total Spray Painting & Panel Beating			\$786.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TOWING CHARGE			\$200.00						
Total Other Costs			\$200.00						
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009898	GLASS	6286730316	GLASS:SIDE,FRONT,RH, FOR MB CITARO O530	1.00	\$1,097.91	10.00	\$988.12		
6009938	GLASS		GLASS,DRIVER'S WINDOW:FIXED,MB O530	1.00	\$1,500.00	10.00	\$1,350.00	Replace	
6009903	BODY RH	6288800272	BUMPER:FRONT,RH,FO R MB CITARO O530	1.00	\$1,754.79	10.00	\$1,579.31	Replace	
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	
4006314			SEALANT SIKAFLEX	6.00	\$37.00	0.00	\$222.00	Replace	
4006313			PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	
6009873	ENGINE	0018106216	MIRROR,VIEW:FRONT RH,AUTO,MB CITARO O530	1.00	\$2,371.83	10.00	\$2,134.65	Replace	
6010143	UNDERCARRIAGE	6287230111	FLAP:FOR MB CITARO O530	1.00	\$48.63	10.00	\$43.77	Replace	
6009508	VE		HEADLAMP FOR MERCEDES OC500 LE, RIGHT	1.00	\$1,276.50	10.00	\$1,148.85	Replace	
6009701	VE		LAMP,BLINKER:FRONT, RIGHT,FOR MB OC500 LE	1.00	\$155.30	10.00	\$139.77	Replace	
6010191	VM	9417500184	FASTENER:FRT BUMPER,FOR MB CITARO BUS	1.00	\$19.35	10.00	\$17.42	Replace	
6010190	VM	9437500084	FASTENER:FRT BUMPER,FOR MB CITARO BUS	1.00	\$64.20	10.00	\$57.78	Replace	
6010182	VM	6288802414	BRACKET:RH,FRT BUMPER,FOR MB CITARO BUS	1.00	\$780.00	10.00	\$702.00	Replace	
Total					\$9,265.51		\$8,543.67		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									