

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2023

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB158P
Case Reference Number	BUS/07/23/7009
Registration Date	21/10/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	CITARO O530
Name of Driver	Zhou Xiaoyong
Type of Accident	Side Swipe
Accident Date and Time	7/7/2023 11:00 AM
Accident Reported Date and Time	7/7/2023 2:20 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB158P - FRONT PORTION GBG5890D (TP) - INSURED WITH INCOME
Prepared Date and Time	10/7/2023 10:41 AM
Chassis Number	WEB62808323122697
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$6,834.94	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$9,940.94	\$0.00
Lump Sum Total	\$9,950.00	\$0.00
Number of Repair Days	5.0	4 days 12/5
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	10/07/2023 10:55 AM	
Signature		
Remarks	Re-insure - H990510068 10/07/23 @ 14:00 Rep after repair	

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757006
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2023

User ID : GohKK2

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,120.00	1590
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	616
Total Spray Painting & Panel Beating	\$786.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	7
Total Other Costs	\$200.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009896	GLASS	6286730316	GLASS:SIDE,FRONT,RH, FOR MB CITARO O530	1.00	\$1,097.91	10.00	\$988.12		bro ✓
6009538	GLASS		GLASS,DRIVER'S WINDOW:FIXED,MB O530	1.00	\$1,500.00	10.00	\$1,350.00	Replace	bro ✓
6009803	BODY RH	6288800272	BUMPER:FRONT,RH,FO R MB CITARO O530	1.00	\$1,754.79	10.00	\$1,579.31	Replace	bro ✓
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	na ✓
4006314			SEALANT SIKAFLEX	6.00	\$37.00	0.00	\$222.00	Replace	na ✓
4006313			PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	na ✓
6009873	ENGINE	0018106216	MIRROR,VIEW:FRONT RH,AUTO,MB CITARO O530	1.00	\$2,371.83	10.00	\$2,134.65	Replace	bro ✓
6010143	UNDERCARRIA GE	6287230111	FLAP:FOR MB CITARO O530	1.00	\$48.63	10.00	\$43.77	Replace	Repair ✓
6009508	VE		HEADLAMP FOR MERCEDES OC500 LE, RIGHT	1.00	\$1,276.50	10.00	\$1,148.85	Replace	bro ✓
6009701	VE		LAMP,BLINKER:FRONT, RIGHT,FOR MB OC500 LE	1.00	\$155.30	10.00	\$139.77	Replace	bro ✓
6010191	VM	9417500184	FASTENER:FRT BUMPER,FOR MB CITARO BUS	1.00	\$19.35	10.00	\$17.42	Replace	na ✓
6010190	VM	9437500084	FASTENER:FRT BUMPER,FOR MB CITARO BUS	1.00	\$64.20	10.00	\$57.78	Replace	na ✓
6010182	VM	6288802414	BRACKET:RH,FRT BUMPER,FOR MB CITARO BUS	1.00	\$780.00	10.00	\$702.00	Replace	bro ✓
Total					\$9,265.51		\$8,543.67		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: