



Repair Estimates  
ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

TP INSURER:  
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

*Jumani  
claim*

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/07/2023
Vehicle Reg. No.:	<b>SHD4682P</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	14/11/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU408617	Chassis No:	KMHC851CVLU189899
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	4,087.44
Miscellaneous Items	11.00
Labour	2,030.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>6,128.44</b>
<b>+ GST 8.00% (S\$)</b>	<b>490.28</b>
<b>Nett Amount (S\$)</b>	<b>6,618.72</b>

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 07 Jul 2023)  
**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD4682P/07/07/2023 16:19  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	de / *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	ur / *22.00 FL
3	1		*REAR BUMPER BEAM	20.00	0.00	? / *394.80 FL
4	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de / *451.25 FL
5	1		*REAR FOG LAMP ASSY	20.00	0.00	cut / *201.50 FL
6	1		*ANTENNA SMARTKEY	20.00	0.00	? / *40.50 FL
7	1		*REAR BUMPER TOW COVER	20.00	0.00	de / *98.80 FL
8	1		*BOOTLID COVER	20.00	0.00	bb / *2,549.70 FL
9	1		*BOOTLID EMBLEM - IONIQ	20.00	0.00	ur / *31.30 FL
10	1		*BOOTLID EMBLEM - HYBRID	20.00	0.00	ur / *24.30 FL
11	1		*BOOTLID EMBLEM - H	20.00	0.00	cut / *28.00 FL
12	1		*BOOTLID GLASS LOWER MOULDING	20.00	0.00	ur / *145.20 FL
13	1		*BOOTLID GLASS UPPER MOULDING	20.00	0.00	ur / *186.30 FL
14	1		*REAR NUMBER PLATE	0.00	0.00	cur / *55.00 F
15	1		*REAR BOOTLID COMFORT LOGO	0.00	0.00	ur / *30.00 F
16	1		*REAR BOOTLID COMFORT TEL NOS. LOGO	0.00	0.00	ur / *30.00 F
17	1		*REAR BOOTLID APPS LOGO	0.00	0.00	ur / *40.00 F
18	1		*REAR WINDSCREEN SEALANT	0.00	0.00	ur / *46.00 F
19	1		*REVERSE SENSOR	0.00	0.00	ur / *180.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,014.05</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>926.61</b>
<b>Total Parts (S\$)</b>	<b>4,087.44</b>

ComfortDelGro Engineering Pte Ltd/SHD4682P/07/07/2023 16:19. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (\$\$)</b>			<u>11.00</u>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	525 1,100.00
2	SPRAY PAINT	New	500 600.00
3	CHECK WIRING	New	30 50.00
4	TUFF KOTE	New	30 50.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	✓ 120.00
6	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
7	TOWING CHARGE	New	✓ 60.00
<b>Gross Labour Cost (\$\$)</b>			<u>2,030.00</u>

ComfortDelGro Engineering Pte Ltd/SHD4682P/07/07/2023 16:19. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS  
 < END OF ESTIMATES >

*Tanji 97495749  
 WP: 6/7/22 @ 5pm  
 3 days  
 1/5 rising after repair  
 tanji e/khauto-wa*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is not on a "no prejudice" basis
- No illerati
- Suspect

Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5903144

JC NO305559900


OMER S COMFORT TRANSPORTATION PTE LTD OMER NO 7010045 ESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO.: SHD4682P	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 06.07.2023 23:00
	YR OF MANU. 14.11.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLU189899	COMPLETION DATE/TIME:

UNIT CARD NO.

JOB DESCRIPTION

Accident Date: 06.07.2023  
 TIME: 3P.06.07.23

NO                      LABOR CODE                      DESCRIPTION



RECEIVED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

Assessment Slip

Exit Pass

Vehicle No.: SHD4682P                      JU TOKIO

Vehicle No.: SHD4682P

\_\_\_\_\_  
 Service Advisor                      Signature/Date

\_\_\_\_\_  
 Name of Service Advisor                      Date

Returned to Service Reception upon collection

To be kept by Security Guard



## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

### Job Requisition

1. Date: <u>6-7-23</u> Time Received: <u>23.10</u>		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)		4. Type of Towing: <input type="checkbox"/> Normal Tow <input checked="" type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	
2. <input type="checkbox"/> New <input checked="" type="checkbox"/> SPARK Kakis Name of Customer: <u>MY WOO</u>		5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery		6. Parts Replaced/Remarks:	
Contact No.: <u>98464224</u>					
Vehicle No.: <u>SHD 4682P</u>					
Make / Model / Colour:					
Email: <u>polix</u>					

7. Location: <u>Sms PI</u>			8. Vehicle Tow - In Workshop:		
9. Preferred Workshop:			<input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed		
<input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan			<input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty		
<input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi			<input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty		
<input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD)			<input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power		
<input type="checkbox"/> Others:			<input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled		
			<input type="checkbox"/> Return Taxi		

10. Odometer Reading : _____		11. Radio / CD Player							
Fuel Level : <table border="1"><tr><td>F</td><td>1/4</td><td>1/2</td><td>3/4</td><td>E</td></tr></table>		F	1/4		1/2	3/4	E	<input checked="" type="checkbox"/> OK	
F	1/4	1/2	3/4		E				
		<input type="checkbox"/> Faulty							
		<input type="checkbox"/> Not tested							

12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input checked="" type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> OTHERS		# : Cracked    X : Dented / : Scatched    O : Missing  Signature of Customer
Name of Driver : <u>LKH</u>		
Vehicle No. : <u>4PL5</u>		
Time Dispatch : <u>22.10</u>		
Time of Arrival : <u>00.05</u>		
Time Completed : _____		

13. Cash Invoice Details (if applicable)	
13. Cash Invoice No. : _____	

Customer Acknowledgement		
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.		
b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.		
c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.		
<u>6-7-23</u>	_____	_____
Date	Time	Signature of Customer

14. WORKSHOP		
_____	_____	_____
Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard