

A.S.S. REC. BY: Taufik

REF:

TM 1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seent _____ Consistent? : Yes or No

Est. Repair: 1 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Juman Vehicle: IN / OUTVeh No: SNC 3181E Yr Regn: 2019 Jan

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Pro c.c. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 368663 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD KB SFU X03078010Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NP / S/Rim / STD A/Rim orTyre Size: F: 145/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 6 D.O.I. 10/7/23Survey held at Compt Logon

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh confirmed lump sum \$1150 and 1 day

(red, \$310, 21%)

Date/Time, File Pass to?

☐ : Prell. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Rep. Format: _____

Lump Sum / I.B.A. ()

Days Of Repair: 1

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Wheelend (\$ _____)

Survey Fee:

Transportation:

S+RS SI

Photos

Others

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

*Jumani
Calsum*

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/07/2023
Vehicle Reg. No.:	SHC3181E	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	06/01/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2B86589	Chassis No:	JTDKB3FUX03078010
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	2		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,149.00
Miscellaneous Items	11.00
Labour	240.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	1,400.00
+ GST 8.00% (\$)	112.00
Nett Amount (\$)	1,512.00

This claim is handled by: JUMANI BIN MASUDIN

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 08 Jul 2023)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC3181E/08/07/2023 10:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT SIDE MIRROR ASSY RH	25.00	0.00	<i>cr</i> *1,390.10 FL
2	1		*FRT SIDE MIRROR COVER RH	25.00	0.00	<i>lis</i> *141.90 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						1,532.00
- List Item Discount on L Items (S\$)						383.00
Total Parts (S\$)						1,149.00

ComfortDelGro Engineering Pte Ltd/SHC3181E/08/07/2023 10:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			11.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEAT	New	120.00
2	SPRAYPAINT	New	120.00
3	TOWLING		
Gross Labour Cost (S\$)			240.00

ComfortDelGro Engineering Pte Ltd/SHC3181E/08/07/2023 10:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

Tanji 97495745
Wp 10/7/23 05pm
• 1 day
1/3 Kery after repair
tanji c (Khanhwan)


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition 1. Date: 07/07/23 Time Received: 1606 2. ☐ New ☐ SPARK Kakis Name of Customer : Mr HAREEN Contact No. : 87813609 Vehicle No. : SAC 3181E Make / Model / Colour : Subaru Prius Email :		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery		6. Parts Replaced/Remarks:	
7. Location: UBF link -		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi	
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:		10. Odometer Reading : 368663 Fuel Level : F 1/4 1/2 3/4 E	
Job Attended 12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ GAO ☐ OTHERS Name of Driver : Balan Vehicle No. : QV5593Z Time Dispatch : Time of Arrival : 1630 Time Completed :		11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested  #: Cracked X: Dented /: Scatched O: Missing Signature of Customer	
Cash Invoice Details (if applicable) 13. Cash Invoice No. :			
Customer Acknowledgement a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
07/07/23 Date		Signature of Customer	
14. WORKSHOP Name of Attending Staff/Guard Date & Time of Arrival Signature of Attending Staff/Guard			