

(08/11/13) Wef

ASS. REC. BY: John

REF:

CS3/HSB 2300 6949/Rnp3

75
2911**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FOA 6482P

at Workshop m/s SINCERE LENO

of H8, TO HAWKINS RD #02-126

Insured: HSB

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 12K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FOA 6482P Yr Regn: 2019 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA YZF R15S C.C. 155

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3244710 KK108517

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70 R17

R: 150/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 4 mm Rear 5 mm


R/Bal. 4 mm L/Bal. 5 mm

L/Bal. 4 mm D.O.A. 20/06/23 D.O.I. 10/07/23

Survey held at SINCERE LENO

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

REPAIR LIMIT - 9KESTIMATE RANGE OF REPAIR / NO. OF MYS - (5K-6K) / 5 days

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	291I
Vehicle Details	
Vehicle No.:	FBQ6482P
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jul 2023
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R155
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	G3J6E0198271
Chassis No.:	MH3RG4710KK108517
Maximum Power Output:	-
Open Market Value:	\$2,927.00
Original Registration Date:	19 Nov 2019
First Registration Date:	19 Nov 2019
Transfer Count:	5
Actual ARF Paid:	\$440.00
PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Information for COE Rebate Payment	
COE Expiry Date:	18 Nov 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,100.00
COE Rebate Amount:	\$2,602.00
Total Rebate Amount:	\$2,602.00

The information contained herein is correct as at 13 Jul 2023

OK