


**GROUND TRANSPORT FLIGHT**

**JOB QUOTATION**

Job Card no : CM / ARJC		JR NO :	
Prepared By Name : Patrick Teo Sign :  Date : 10/7/2023		Vetted By Name : Mr Ivan Chin Sign : Via e-mail Date : 10/7/2023	
		Vehicle No. : MID 46310 Type : Nissan Mini Bus	

S/N	SERVICE DESCRIPTION	PROPOSED	
		MANHOURS / COST	MATERIALS / COST
1 SUB- CONTRACT SERVICES:-			
A. LABOUR:- LH Side Bumper, Panel and Door Dented, LH Side Signal Lamp Broken			
1	Repair front LH bumper, LH corner panel, LH Door. Spray paint on affected area ( LH bumper, LH corner panel, LH door and side step )	S\$ 650.00	
		S\$ -	
		S\$ -	
	8% MARK- UP	S\$ 52.00	
B. MATERIALS:-			
1	Supply LH Side Lamp		S\$ -
			S\$ -
	7% MARK- UP		S\$ -
2 IEPL SERVICES:-			
A. LABOUR:-			
1	In processing and final inspection (2 x manhr to drive vehicle to and back from workshop, 1 x manhr for final inspection)	S\$ 72.99	
	1 x manhr \$24.33	S\$ -	
B. MATERIALS:-			
			S\$ -
			S\$ -
	7% MARK- UP		S\$ -
	SUB-TOTAL	S\$ 774.99	S\$ -
	GRAND TOTAL	S\$	774.99

PROPOSED TAT		ACKNOWLEDGED BY OC		
DAYS	MH / TOTAL COST	DATE	SIGN	RANK/NAME
7 Days	S\$ 774.99			

VALIDITY OF THIS QUOTE IS 30 DAYS FROM THE DATE OF THIS QUOTATION