

**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2023  
User ID : GohKK2

Section A - Accident Details	
Registration Number	SG6107A
Case Reference Number	BUS/06/23/7038
Registration Date	23/8/2019
Company Type	SMRT Buses Ltd
Make	
Model	MAN A95
Name of Driver	Zhang Chun
Type of Accident	Side Swipe
Accident Date and Time	29/6/2023 12:52 PM
Accident Reported Date and Time	3/7/2023 6:09 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG6107A - REAR RIGHT PORTION SLA708U (TP) - INSURED WITH AIG
Prepared Date and Time	10/7/2023 1:35 PM
Chassis Number	WMAA95Z20KF008854
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$354.00	\$0.00
Total Spare Part Cost	\$345.60	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$1,494.60</b>	<b>\$0.00</b>
Lump Sum Total	\$1,500.00	\$0.00
Number of Repair Days	3.0	2 days / L15
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	10/07/2023 1:42 PM	
Signature:	<i>[Signature]</i>	<i>[Signature]</i>
Remarks		Prime - 4x 900mls 10/07/23 @ 1450 Pkg after repair

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

**SMRT Automotive Services Pte Ltd**  
60 Woodlands Industrial Park E4, Singapore 757906  
FAX Number : 63685552  
Estimator Telephone Number : 68662623  
Accident Reporting Number : 68662672

Date Generated : 10/07/2023

User ID : GohKKZ

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED / AFFECTED AREAS	\$795.00	530
<b>Total Labour</b>	<b>\$795.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPIRAY ABOVE REPAIR ITEMS	\$354.00	262
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$354.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013696	VE	36-25225-8004	REAR LAMP BULB (ABS MAIN)	1.00	\$220.00	10.00	\$198.00	Replace	can
6013696	VE	36-25183-8001	REVERSE LAMP	1.00	\$215.00	10.00	\$193.50	Replace	can
6013692	Body	124-22-019-012	ONE PRP REAR LAMP	1.00	\$0.00	100.00	\$0.00	Repair	Repair
<b>Total</b>					<b>\$1,455.00</b>		<b>\$432.00</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_