

Service Request Details

Claim	S3M04NXS
Reference	CS3/HSB23006953/Tnp3m4 
Loss Date	7 July 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	10 Jul 2023 11:49:13 AM
Request Date	10 July 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information	
Incident	GBM3922C
Vehicle	
Registration #	
Make	TPVD DFSK
Model	EC31
Service Address	
, , ,	
Primary Contact/Insured	

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOW Garnet

garnet.low@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 HSB-LKKInvoice-AC2304560.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2023
 Resurvey photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2023
 Resurvey photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2023
 GBM 3922C-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 July 2023
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	10 July 2023
 SHA2729T INSD GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	10 July 2023
 TP GIA REPORT - GBM3922C.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh	10 July 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
			Pandurang	
 REPLY FROM SOLICITOR.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	10 July 2023