

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

CP/P)

Singapore

LKK -

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/07/2023
Vehicle Reg. No.:	SHA9019M	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	28/04/2022
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	2ZR2P76968	Chassis No:	JTDKB3FUX03096409
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,814.77
Miscellaneous Items	11.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,405.77
+ GST 8.00% (S\$)	352.46
Nett Amount (S\$)	4,758.23

This claim is handled by: LIM TIEN SIONG

10/7 @ 14:59 hrs

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 10 Jul 2023) **Lim Tien Siong**

Parts: 144 **TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA9019M/10/07/2023 14:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	25.00	0.00	<i>in</i> *591.75 FL
2	1		*FRONT BUMPER SIDE BRKT LH	25.00	0.00	<i>dt</i> *82.30 FL
3	10		*FRONT BUMPER CLIPS	25.00	0.00	<i>ner</i> *22.00 FL
4	1		*FRONT FENDER LH	25.00	0.00	<i>bd</i> *1,111.93 FL
5	1		*FRONT FENDER (HYBRID) LH	25.00	0.00	<i>ner</i> *86.50 FL
6	1		*FRONT WHEEL RIM LH	25.00	0.00	<i>X</i> *1,570.55 FL
7	1		*FRONT WHEEL TYRE LH	0.00	0.00	<i>X</i> *216.00 F
				Sub Total (S\$)		3,681.03
				- List Item Discount on L Items (S\$)		866.26
				Total Parts (S\$)		2,814.77

ComfortDelGro Engineering Pte Ltd/SHA9019M/10/07/2023 14:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Lim Tien Siong

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350

800.00

2 SPRAY PAINTING

New

500

600.00

3 TUFF KOTE

New

30

60.00

4 WHEEL ALIGNMENT

New

X

120.00

Gross Labour Cost (S\$)

1,580.00

ComfortDelGro Engineering Pte Ltd/SHA9019M/10/07/2023 14:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749
WP/ 11/8/23 @ 1030am
P/P Resurvey before paint
2 days
tanpin@khawp.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "no prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 10.07.2023 15:03

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD

Sales Order: 5903384

JC NO305560143

S CITYCAB PTE LTD
OMER NO. 7010070
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188
(P) (O)

JUNT CARD NO.


REGN NO.: SHA9019M	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4A10.	DATE/TIME IN 07.2023 10:55
YR OF MANU. 28.04.2022	TARGET DATE
CHASSIS CODE JTDKB3FUX03096409	COMPLETION DATE/TIME:

Incident Date: 08.07.2023
TURE: 3P 08.07.2023/C

JOB DESCRIPTION

NO LABOR CODE
00010 PB
00020 SP
00030 20-00

DESCRIPTION
PANEL BEATING-SHA9019M-TP
SPRAYPAINT CHARGE
TUFF COAT ON AFFECTED PARTS.



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHA9019M LIMITS

Vehicle No.: SHA9019M

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard