

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD	F	Ref:	CS/SMR23006996/Kvy3m4	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 17705	С	Date:	21/07/2023	
			C	Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHB 1733G	Veh. Inspected		SLR 2428A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/07/23/2015	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		10/07/2023	
2. Vehicle Particulars & Condition						
	Make & Model	KIA CERATO (A)	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	KNAFX411MJ5729465	Colour		METALLIC SILVER	
	Odometer	63782 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55R16	MICHELIN		8 mm	
	L/H Front Tyre	205/55R16	MICHELIN		8 mm	
	R/H Rear Tyre	205/55R16	MICHELIN		8 mm	
	L/H Rear Tyre	205/55R16	MICHELIN		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/07/2023	Inspection Date		11/07/2023	
	Survey held at SERVE YOU MOTOR SERVICE  BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					
	•					