SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Tomies de la comite de la comit

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

8/07/2023

Sketch Plan

A Columbia

A Col

vJun2022

A: SHO 1187 Y' B: SDY 1211 Y

Describe Circumstances of the Accident.


ON 07/07/2023 @ 22:40HRS, I WAS DRIVING MY TAXI (SHD1187Y/HYUNDAI 130(A)/SILVERCAB), TRAVELLING ALONG PIE - TOWARDS TAMPINES STREET 45, WITH 1 MALE AND 3 FEMALE PASSENGERS ONBOARD, IN LANE 2.

I WAS PROCEEDING STRAIGHT AHEAD WITHIN MY OWN LANE, SUDDENLY I FELT AN IMPACT FROM THE LEFT. VEHICLE B (SDY 1211 Y - LEXUS ES300) WHICH WAS INITIALLY TRAVELLING IN LANE 3, HAD ENCROACHED INTO MY LANE, CAUSING VEHICLE B'S RIGHT PORTION TO HIT AGAINST MY TAXI'S LEFT PORITON.

DUE TO THE IMPACT, MY TAXI SUSTAINED DAMAGES ON THE LEFT PORTION. I WAS NOT AWARE IF VEHICLE B SUSTAINED ANY DAMAGES.

NO INJURY INVOLVED. UNKNOWN PASSENGERS ONBOARD VEHICLE B.

NO AMBULANCE AT SCENE.



Text size +

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert 200304975H

Owner ID Type:

Company

Owner Name:

PREMIER TAXIS PTE, LTD.

Registered Address:

23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address:

Birth Date:

Vehicle Particulars

Vehicle No.:

SHD1187Y

Previous Vehicle No.:

Effective Date of Ownership:

25 Jan 2017

Original Regn Date:

25 Jan 2017

Registration Date:

25 Jan 2017

Year of Manufacture:

2016

Vehicle Type:

Public Transport Taxi (Motor Car)

Vehicle Scheme:

Taxi (Company)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

HYUNDAL

Vehicle Make: Vehicle Model:

130 GDH 1.6 TCI 5DR DCT

Primary Colour;

Silver

Secondary Colour.

Passenger Capacity:

TMAD281UVHJ119084

Engine No.:

D4FBGZ096080

Engine Capacity/Power

1582 cc / -

Rating: Maximum Power Output:

Chassis No.:

100.0 kW (134 bhp)

Propellant:

Diesel

Max Unladen Weight:

1496 kg

Maximum Laden Weight:

1940 kg \$20,830,00

Open Market Value: PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Jan 2025

Minimum PARF Benefit:

\$8,197.00

No. of Transfers: IU Label No .:

٥

1050703206

COE No.: COE Expiry Date: 2017012501003871Z

24 Jan 2025

COE Calegory:

A - Car (up to 1600cc & 97kW (130bhp))

COE Registration Category:

A - Car (up to 1600cc & 97kW (130bhp))

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SDY1211Y

Date of Accident

07/07/2023 🛱

Reset

% RESULT & RECEIPT

TP Insurer Enquiry	
Insurance	Allianz Insurance Singapore P
Period of Insurance	23/03/2023 - 22/03/2024
Requested By	VINCENT CHUA WEE AN (PREM
Requested Date	08/07/2023 11:50

Payment details

Request Amount: **\$\$1.85** GST Amount: **\$\$0.15**

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: **M400017735**