

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23007058/Dvp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	17-07-2023 INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLK 2747R	Veh. Ir	spected	SHA 4469E	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1229869-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	30/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU903559432	Coloui	•	BLUE	
	Odometer	803018	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST I		5 mm	
	L/H Front Tyre	195/65 R15	WEST I	_AKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST I	_AKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST I	_AKE	5 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	28/06/2023	Inspec	tion Date	30/06/2023	
	Survey held at	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969				
5a.	<del>_</del>					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					