

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI23007062/Uqy3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	re: 21/07/2023	
			Cod	de: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMQ 4066R	Veh. Inspected	SJX 2355T	
	Policy No.	P10811081R00	Coverage (\$)	0.00	
	Claim No.	C10023411 /JY	Excess (\$)	0.00	
	Assign From		Assign Date	12/07/2023	
2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO KOUP SX (M)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	KNAFW611LA5231140	Colour	RED	
	Odometer	254145 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
	L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
	R/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
	L/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/07/2023	Inspection Date	12/07/2023	
	Survey held at TK LEE AUTOMOTIVE PTE LTD				
	NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883				
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: