

KY AUTO

25, KAKI BUKIT ROAD 4,
#05-23, SYNERGY,
SINGAPORE 417800

TEL : 9807 3304

Customer

Vehicle ident no.

Repair order no.
R006408

Technician

Date
12.7.23

License plate no.
SFN6462R

First reg. date

Model

Toyota : Altis

Odometer reading: km/miles
434036

Complaints or reason for alignment check

			Before	Target Data		Actual
Rear axle	Camber	left	-2°02' *	-1°29'	+/-0°30'	-2°02' *
		right	-1°15'			-1°15'
		cross	-0°47' *	0°00'	+/-0°30'	-0°47' *
	Toe	left	-0°07' *	0°07'	+/-0°06'	-0°07' *
		right	0°27' *			0°27' *
		total	0°20'	0°14'	+/-0°12'	0°20'
Geometrical driving axis		-0°17'	0°00'		-0°17'	
Front axle	Camber	left	-1°57' *	-0°34'	+/-0°45'	-1°57' *
		right	0°43' *			0°43' *
		cross	-2°40' *	0°00'	+/-0°30'	-2°40' *
	Caster	left	2°05' *	2°58'	+/-0°45'	2°05' *
		right	2°30'			2°30'
		cross	-0°25'	0°00'	+/-0°30'	-0°25'
	SAI	left	17°03'	12°32'		17°03'
		right	11°31'			11°31'
		cross	5°32'	0°00'		5°32'
	Track differential angle	left				
		right				
	Toe	left	0°50' *	0°00'	+/-0°05'	1°02' *
		right	0°50' *			0°37' *
		total	1°39' *	0°00'	+/-0°09'	1°39' *
Setback			0°00'			
Max steering lock	left steer	left		-38°13'	+/-2°00'	
		right		32°49'	+/-2°00'	
	right steer	left		32°49'	+/-2°00'	
		right		-38°13'	+/-2°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.