

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMR23007064/4ny3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: STN 6462R
at Workshop m/s Ky Ave 05-23

of _____

Insured: SG 5424R

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: 9k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 25 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 3 8237

Date: _____ Person Contacted: _____

Veh No: STN 6462R Yr Regn: 20/07/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota Corolla AHS c.c. 1598

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 434036 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MROS37EE106149935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or ok

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: Ecocru

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 3 mm Rear 5 mm

R/Bal. 3 mm R/Bal. 5 mm

L/Bal. 3 Nil rim mm L/Bal. 5 mm

D.O.A. 02/07/23 D.O.I. 12/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/5 Rpt, N/S Rpt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27 10k.

coe unv / 30-06-2024 LTA 2884

30/11/24 NHT 6116

19/7/23 insured Isabelle 4/5 858w (Red. \$13107.77, 69%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	823J
Vehicle Details	
Vehicle No.:	SFN6462R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	3ZZ4913240
Chassis No.:	MR053ZEE106149935
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,500.00
Original Registration Date:	20 Jul 2009
First Registration Date:	20 Jul 2009
Transfer Count:	4
Actual ARF Paid:	\$17,500.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,920.00
COE Rebate Amount:	\$2,884.00
Total Rebate Amount:	\$2,884.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Jul 2023

OK

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices!
Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



Flexible Financing . Loan by GV
Cars Financing at 3.28% p.a.
GV Automobile Centre StarAd



Sort by Date Posted 20 results/page

9 vehicles



ALTIS 2024

Any Category

Advanced Search

Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	ALTIS 2024		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota	Corolla Altis 1.6A (COE till 04/2024)	\$12,000	\$14,950 /yr	06-Jul-2009	1,598 cc	158,537 km	Sedan	Available
Probably One Of The Best Condition Toyota Altis 1.6A! Another 11 Months To Drive And Guaranteed You Will Get Good Export Value Wh...									
Posted: 11-Jul-2023									
	Toyota	Corolla Altis 1.6A (COE till 04/2024)	\$13,800	\$17,800 /yr	21-Apr-2009	1,598 cc	-	Sedan	Available
Careful owner, well maintained, fuel efficiency, easy financing, flexible loan available, accident free, 6 months free servicing by reputable...									
SG Car Choice Pte Ltd									
Posted: 08-Jul-2023									
	Toyota	Corolla Altis 1.6A (COE till 12/2024)	\$19,000	\$13,160 /yr	21-Dec-2009	1,598 cc	136,238 km	Sedan	Available
Drive with assurance with 5-stars reviews. no repairs needed, beautiful condition in in the market with guaranteed in the market. Fully...									
Posted: 07-Jul-2023									
	Toyota	Corolla Altis 1.6A (COE till 06/2024)	\$13,800	\$15,400 /yr	04-Jun-2009	1,598 cc	175,000 km	Sedan	Available
Very well maintained inside out! Perfect for short term usage! Cash & carry! Hurry down today to view and test yourself! Don't miss!									
AA Trust Automotive									
Posted: 05-Jul-2023									
	Is your COE expiring? Let us help you renew it!								
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Toyota	Corolla Altis 1.6A (COE till 09/2024)	\$16,000	\$13,610 /yr	14-Sep-2009	1,598 cc	150,000 km	Sedan	Available
Pristine condition with past servicing records, original leather paintwork since day1, high trade in, Flexible loans packages are available....									
This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More									
Posted: 04-Jul-2023									
	Toyota	Corolla Altis 1.6A (COE till 03/2024)	\$9,800	\$15,030 /yr	07-Mar-2009	1,598 cc	143,377 km	Sedan	Available
Compare	Low mileage car in good condition. Selling in low price contact for viewing and well maintained please call up for an appointment.								

[Compare](#)[PREMIUM AD](#)[DIRECT OWNER](#)

KY AUTO

25, KAKI BUKIT ROAD 4,
#05-23, SYNERGY,
SINGAPORE 417800

TEL : 9807 3304

Customer

Vehicle ident no.

Repair order no.
R006408

Technician

Date
12.7.23

License plate no.
SFN6462R

First reg. date

Model
Toyota : Altis

Odometer reading: km/miles
434036

Complaints or reason for alignment check

			Before	Target Data		Actual
Rear axle	Camber	left	-2°02' *	-1°29'	+/-0°30'	-2°02' *
		right	-1°15'			-1°15'
		cross	-0°47' *	0°00'	+/-0°30'	-0°47' *
	Toe	left	-0°07' *	0°07'	+/-0°06'	-0°07' *
		right	0°27' *			0°27' *
		total	0°20'	0°14'	+/-0°12'	0°20'
	Geometrical driving axis		-0°17'	0°00'		-0°17'
Front axle	Camber	left	-1°57' *	-0°34'	+/-0°45'	-1°57' *
		right	0°43' *			0°43' *
		cross	-2°40' *	0°00'	+/-0°30'	-2°40' *
	Caster	left	2°05' *	2°58'	+/-0°45'	2°05' *
		right	2°30'			2°30'
		cross	-0°25'	0°00'	+/-0°30'	-0°25'
	SAI	left	17°03'	12°32'		17°03'
		right	11°31'			11°31'
		cross	5°32'	0°00'		5°32'
	Track differential angle	left				
		right				
	Toe	left	0°50' *	0°00'	+/-0°05'	1°02' *
		right	0°50' *			0°37' *
		total	1°39' *	0°00'	+/-0°09'	1°39' *
	Setback			0°00'		
Max steering lock	left steer	left		-38°13'	+/-2°00'	
		right		32°49'	+/-2°00'	
	right steer	left		32°49'	+/-2°00'	
		right		-38°13'	+/-2°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email : kyautosg@gmail.com

SFN6462R Toyota Corolla Altis

Damaged Area: Front Right and Left Side

Date: 12/07/2023

D.O.A 02/07/2023

not Authorized
12/7/23
1/5 @ 5800
4 days

→ SG54242
(MSfirst)

Parts / Material :

1	Front bumper	25	558.10	\$ 986.40	✓
2	Front bumper reinforcement	20		\$ 355.90	✓
3	Front bumper bracket ^{retainer} @ SGD 68.90	2 set/cm		\$ 137.80	✓
4	Front bumper fog lamp @ SGD 298.70	11		\$ 597.40	X
5	Front bumper fog lamp garnish @ SGD 75.60	11		\$ 151.20	X
6	Front bumper clips	RM	SV	\$ 55.00	✓
7	Headlamp assy @ SGD 768.40	MS11 o/s one	645.10	\$ 1,536.80	12C
8	Front fender @ SGD 786.90	MS11 o/s 2 set		\$ 1,573.80	12C
9	Front fender inner shield @ SGD 195.80	2 set/cm		\$ 391.60	✓
10	Front fender inner shield clips 2set	RM		\$ 80.00	✓
11	Front fender quarter moulding o/s	11		\$ 115.60	X
12	Front fender lamp emblem VVTI (wordings) @ SGD 65.20	11		\$ 130.40	X
13	Wing mirror assy w/lamp o/s	11		\$ 495.80	X
14	Front door o/s	11		\$ 1,001.90	X
15	Front door upper hinge o/s	11		\$ 95.20	X
16	Front door lower hinge o/s	11		\$ 92.40	X
17	Front door inner trimboard clips	11		\$ 50.00	X
18	Rocker garnish o/s	11		\$ 320.60	X
19	Rocker garnish clips	11		\$ 55.00	X
20	Front cross member	11		\$ 1,286.90	X
21	Front steering rack & pinion	11		\$ 1,496.80	X
22	Shock absorber @ SGD 430.20	2 set/cm		\$ 860.40	✓
23	Front lower arm @ SGD 495.80	2 set		\$ 991.60	✓
24	Front knuckle arm @ SGD 565.80	2 set		\$ 1,131.60	✓
25	Front steering ball joint @ SGD 155.70	2 set	121.30 x 2 = 242.60	\$ 311.40	✓
26	Front knuckle hub bearing @ SGD 435.20	RM	265 x 2 = 530	\$ 870.40	✓
27	Front dri-shaft @ SGD 1015.90	11		\$ 2,031.80	X

Parts : \$17,203.70

Less Parts 25% : \$ 4,300.92

Total Parts : \$12,902.77

Special Net Items :

Front sport rim @ SGD 550.00

*sent/merged**N/S 505/N 0/5 400*

\$ 1,100.00

450

Front tyre @ SGD 420.00

11

\$ 840.00

X

Front number plate w/garnish

11

\$ 45.00

*X***Total S/N Parts : \$ 1,985.00****Labour :**

To Repair, Remove & Renew On Affected Accident Areas @ SGD 350.00 per day

\$ 1,100.00

500

To Putty, Spray Paint on Affected Accident Areas @ SGD 300.00 per panel

\$ 1,500.00

850

To Check & Re-Connect all electrical wiring

\$ 50.00

20

To Remove & Transfer Sport Rim & Tyre, To Conduct Tyre Balance

11

\$ 120.00

X

To Remove & Transfer Front Undercarriage Components to Facilitate Repairs

\$ 250.00

✓

To Conduct Computerised Wheel Alignment

\$ 150.00

100

To Remove & Install Front Door Components To Facilitate Repairs

11

\$ 150.00

X

To Conduct & Reset ECU Diagnostic Programme

11

\$ 450.00

X

To Rust Proof Affected Areas

\$ 250.00

*30***Total Labour : \$ 4,020.00****TOTAL PARTS : \$ 12,902.77****TOTAL SPECIAL NET ITEM: \$ 1,985.00****TOTAL LABOUR : \$ 4,020.00****TOTAL REPAIR COST : \$ 18,907.77**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6761.6
253

5071.2
450

1150

7271.2
202

5816