

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

while making negotiating a left turn at roundabout towards Scotts Rd when a m/lorry (YN5171L) come fast and sideswipe with my bus. Bus right front damaged and lorry left side body scratched. No one was injured. Bus was arranged off service to AMD after exchanged particulars with lorry driver and consulted CRS.

ATTACHMENT(S)

Are accident photos available for attachment? No
Was there any video captured by Car Camera? No