

# ACCIDENT INVOLVING MID 41695 and SKW7026D & SLG1107R on 040723

## SCHEMATICS




Figure A-1

STATEMENT OF	SSG LIOW TIA HWEE, GIBSON				ALIASES			
NRIC NO.	SXXXX301J		AGE	26	MALE / FEMALE		MALE	
EMPLOYMENT	REGULAR				NATIONALITY		SINGAPOREAN	
DIALECT	HOKKIEN	LANGUAGE SPOKEN	ENGLISH		CONTACT NO.		[REDACTED]	
ADDRESS	[REDACTED]							
INTERPRETED BY		RANK		TIME		DATE		SIGN
RECORDED BY	GERALD	RANK	2LT	TIME	1515	DATE	0407	SIGN
<p>I, SXXXX301J, SSG LIOW TIA HWEE GIBSON, ON TUESDAY, 040723 AT ABOUT 1301HRS WAS DRIVING A NISSAN SYLPHY MILITARY VEHICLE BEARING THE PLATE NUMBER OF MID 41695 / SNA 7413A, ENROUTING TOWARDS CLEMENTI CAMP FROM BEDOK CORNER FOOD CENTRE. AT ABOUT 1314HRS, I WAS DRIVING SLOWLY BEHIND A VAN ALONG UPPER CHANGI ROAD JUST BEFORE CHANGI FIRE STATION WHERE OUT OF A SUDDEN THE VAN IN FRONT OF ME CAME TO A STOP, TO WHICH I CAME TO A STOP AS WELL. HOWEVER SECONDS LATER, OUR MILITARY VEHICLE GOT REAR ENDED BY ANOTHER CIVILIAN VEHICLE (SKW7026D) THAT WAS REAR ENDED BY ANOTHER CIVILIAN VEHICLE (SLG1107R). I WAS THE TRANSPORT OPERATOR FOR THE VEHICLE AND 3SG MOHAMAD YUSRI MOHAMED YUSSOFF WAS THE VEHICLE COMMANDER. NO OTHER PERSONNEL INVOLVED INCURRED ANY INJURIES LESS MYSELF WITH BACKPAIN. THE MILITARY VEHICLE REAR BUMPER AND RIGHT REAR BUMPER IS DENTED AND BOTH CIVILIAN VEHICLES ARE DAMAGED AS WELL.</p>								
DATE / TIME	040723 1515H			SIGNATURE OF WITNESS		< SENT VIA E-MAIL >		

Figure B-1: Statement of driver

STATEMENT OF	3SG MOHAMAD YUSRI MOHAMED YUSSOFF				ALIASES				
NRIC NO.	TXXXX896B	AGE	20	MALE / FEMALE	MALE				
EMPLOYMENT	NSF			NATIONALITY	SINGAPOREAN				
DIALECT	MALAY	LANGUAGE SPOKEN	ENGLISH, MALAY	CONTACT NO.	[REDACTED]				
ADDRESS	[REDACTED]								
INTERPRETED BY		RANK		TIME		DATE		SIGN	
RECORDED BY		RANK		TIME		DATE		SIGN	
<p>I, TXXXX896B 3SG MOHAMAD YUSRI MOHAMED YUSSOFF ON 04 JULY 2023 AT 1314HRS WAS THE VEHICLE COMMANDER FOR SSG GIBSON, WHO WAS DRIVING NISSAN SYLPHY (MID 41695) FOR DESERTER OPS RECCE. WHILE WE WERE ENROUTE TO POL AT CLEMENTI CAMP AFTER OUR DESERTER OPS RECCE, ALONG UPPER CHANGI RD, OUR VEHICLE WAS REAR ENDED BY A CIVILIAN VEHICLE (SKW 7026D) THAT WAS ALSO REAR ENDED BY ANOTHER CIVILIAN VEHICLE (SLG1107R), RIGHT BEFORE CHANGI FIRE STATION. THERE WERE DAMAGES SUSTAINED BY OUR VEHICLE AND THE TWO CIVILIAN VEHICLES. WE STOPPED THE VEHICLE AND EXCHANGED DETAILS WITH THE TWO OTHER DRIVERS. PICTURES OF THE VEHICLE WERE TAKEN AS EVIDENCE.</p>									
DATE / TIME	040723 1600H		SIGNATURE OF WITNESS		< SENT VIA E-MAIL >				

Figure B-2: Statement of driver



**SINGAPORE  
POLICE FORCE**



T/20230704/7041

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 4

Report No. T/20230704/7041

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 04/07/2023 14:31		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: LIEW TIA HWEE, GIBSON			Address: [REDACTED]		
ID Type / ID No.: NRIC NO / [REDACTED] 301J			Contact No.: Home/Office: [REDACTED] Mobile: [REDACTED]		
Nationality: SINGAPORE CITIZEN			Email: [REDACTED]		
Sex: Male	Age: 26	Date of Birth: 06/08/1996	Type of Informant: Driver		
Race: Chinese			Language: English		
Occupation: Other government associate professionals			Driving Licence Information: Class: [REDACTED] Date of Expiry: [REDACTED]		

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 04/07/2023 13:10	Type of Location: Straight Road
Location:  UPPER CHANGI ROAD				
Weather: Clear		Road Surface: Dry		
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
SKW7026D	Car	HONDA	VEZEL	White	Slightly Damaged	1
SLG1107R	Car	MERCEDES BENZ		Red	Slightly Damaged	0
SNA7413A	Car					0

Figure C-1 Police report part 1



**SINGAPORE  
POLICE FORCE**



T/20230704/7041

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4

Report No. T/20230704/7041

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	FOO LILIAN	ID No.	672F
Related Vehicle	SKW7026D (Car)	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
<b>Driver</b>			
Name	BOEY MAO DE JAMES	ID No.	363A
Related Vehicle	SLG1107R (Car)	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
<b>Passenger</b>			
Name	TAN YI HANG	ID No.	857B
Related Vehicle	SNA7413A (Car)	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Figure C-2 Police report part 2



**SINGAPORE  
POLICE FORCE**



T/20230704/7041

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 4

Report No. T/20230704/7041

**CONTINUATION OF REPORT**

<b>Passenger</b>			
Name	MOHAMAD YUSRI MOHAMED YUSSOFF		ID No. [REDACTED] 396B
Related Vehicle	SNA7413A (Car)		Contact No. [REDACTED]
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date	NIL		Date NIL
No. of Days granted Medical Leave	NIL		Degree of NIL
<b>Driver</b>			
Name	LIOW TIA HWEE, GIBSON		ID No. [REDACTED] 301J
Related Vehicle	SNA7413A (Car)		Contact No. [REDACTED]
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date	NIL		Date NIL
No. of Days granted Medical Leave	NIL		Degree of NIL

**Brief Details.**

Date & Time of incident:  
040723, Around 1314HRS

Location of incident:  
Traffic light just before Changi Fire Station

**Brief Description of incident:**

On 040723, at around 1314HRS, I am driving towards CLEMENTI CAMP, I was driving slowly behind a van at Upper Changi Rd and came to a stop just before a traffic light right before Changi Fire Station, where I was rear ended by a civilian vehicle(SKW7026D) that was rear ended by another civilian car(SLG1107R). I was the driver for my vehicle, Nissan Sylphy (MID41695/SNA 7413A)

There was no injuries to personnel onboard & the civilians involved.

My vehicle's rear bumper and right rear bumper is dented and the two civilian vehicles are both damaged.

Contact info was exchanged between all parties.

Note: I have Photos & Videos exceeding 2MB

Figure C-3 Police report part 3



**SINGAPORE  
POLICE FORCE**



T/20230704/7041

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

4 of 4

Report No. T/20230704/7041

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 04/07/2023 14:31
Officer In Charge Of Case: TP / TPIB / FADLI SHAIFUDDIN BIN MOHAMED SANI Contact No.: 65476845	Classification Of Case:

NP168

Figure C-4: Police Report part 4





Figure D1: Damage to rear end of SNA7413A/MID41695



Figure D2: Damage to rear end of SNA7413A/MID41695





Figure D3: Damage photos of SKW7026D



Figure D4: Damage photos of SKW7026D





Figure D5: Damage photos of SLG1107R



Figure D6: Damage photos of SLG1107R